

EFI Vutek GS 3250LX Pro (Press B) – Serial

- Latest jet test (nozzle test) print
 - 4/28/26, have print
- Latest printhead alignment/calibration print
 - 4/28/26, have print
- Full service history (not summary—actual records)
 - Provided
- Video of machine printing live job
 - Provided
- Confirmation of all known issues

PRINthead & INK SYSTEM

- Total printhead hours + list of replaced heads (with dates)
 - 24,888 print hours
 - Heads: see service history, 1 refurbished 12PL head 2026
- Date of last ink filter replacement
 - May 2025
- Ink type used (OEM vs third-party)
 - Gandy third-party inks
- Any history of clogging, banding, or color dropout
 - N/A

CRITICAL FAILURE POINTS (YES/NO + DETAILS REQUIRED)

- Winder/unwinder side holders replaced? When?
 - Never replaced

- Roll feed & tension system fully functional? Any slipping/skewing?
 - Feeds straight from middle of belt but sometimes skews when printing from either side
- Exhaust system installed and working? (Confirm physically present)
 - Yes, fully functional without issue
- Any recurring mechanical or electrical faults?
 - N/A

CONDITION & USAGE

- Any major breakdowns.
 - No major breakdowns

SOFTWARE & TRANSFER

- RIP in use (e.g., Fiery XF) + license transfer confirmation
 - Fiery Command Workstation 7, update 7.1.0.471