



ULTRASONIC THICKNESS INSPECTION REPORT

SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
www.slickinspection.com

Technician Sign: 

Technician Certification:

BRANDON FLAIG
CGSB Level II MT REG.#32777
CWB LEVEL 1 INSPECTOR
REG. #12190660

Assistant: _____

Date: _____

OCT.21 2026

Client: _____

RARE OILFIELD

Location: _____

RARE OILFIELD SHOP
REDCLIFF AB.

Client Rep Signature: _____

KELLY HOBMAN

Upon approval/acceptance by the Contractor the liability for the accuracy of final product becomes responsibility of the Contractor

Invoice #:

BF26212

Report #:

BF26212-U1

Page:

1 of 2

Acceptance Code:

Client Information

Specification:

Integrity Survey

Procedure:

UT-1 Rev.2

Technique:

UT - Thickness

Contractor:

RARE OILFIELD

A.F.E.#:

Code.#:

P.O.#:

Project:

40BBL TANK

Job.#:

TANK SERIAL #16220

40BBL TANK SERIAL #16220 THICKNESS TEST

DATA PLATE



Overview 1



OVERVIEW 2



THICKNESS TESTING PERFORMED ON VESSEL ABOVE ON RANDOM SPOTS ON SHELL/ FLOOR AND ROOF AS PER CUSTOMER. RESULTS ARE RECORDED ON THE FOLLOWING PAGE.

Equipment, Calibrations & Consumables Used

Instrument Make:	AlphaGage+, Ser: 000128	Range Of Verification: 0.1" - 0.5"	Calibrated On: OCT.21 2026	Cable Length: 3 Feet	Cable Type: Coaxial	Test Method: Thickness>  Lamination>	Couplant: Sonotech Soundsafe
Transducer Settings:	Sonatest Probe	Model: DK525	Calibrated On: OCT.21 2026	Angle: 0°	Frequency: 5 MHz	Size: 5 / .25"	Reference & Scan /
Calibration Block:	IIW Type 1 Reference Block 1018 Steel Heat #C203714	Block Serial #: S/N 3142 24	Calibrated On: OCT.21 2026	Reference Reflector: Backwall	Reference %FSH 100%	Range Setting 1.0 Inches	



ULTRASONIC THICKNESS INSPECTION REPORT

Invoice #:

BF26212

Report #:

BF26212-U1

Page:

2 of 2

Technician Sign:

Date:

OCT.21 2026

Client:

RARE OILFIELD

Acceptance Code:

Client Information

Specification:

Integrity Survey

Procedure:

UT-1 Rev.2

Technique:

UT - Thickness

Contractor:

RARE OILFIELD

AFE:

Code:

P.O.#:

Project:

40BBL TANK

Job#:

TANK SERIAL #16220

SLICK INSPECTION LTD.
2038-12th AVE NW
Medicine Hat, AB, T1C 2A7
PH: 403-527-9854
FAX: 403-527-9867
www.slickinspection.com

Technician Certification:

BRANDON FLAIG
CGSB Level II MT REG.#32777
CWB LEVEL 1 INSPECTOR
REG. #12190660

Location:

RARE OILFIELD SHOP
REDCLIFF AB.

Client Rep Signature:

Assistant:

Upon approval/acceptance by the Contractor the liability for the accuracy of final product becomes responsibility of the Contractor

Area Surface Readings: ↓			Nominal Wall Thickness:>			Average Thickness Reading:>			0.202			Area Surface Readings: ↓			Nominal Wall Thickness:>			Average Thickness Reading:>			0.206		
Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:	Location #:	Thickness Min:	Thickness Max:
CML-1	0.188	0.198	CML-6	0.2	0.204	CML-11	0.198	0.214	CML-6			CML-6			CML-6			CML-6			CML-6		
CML-2	0.201	0.21	CML-7	0.204	0.212	CML-12	0.195	0.215	CML-7			CML-7			CML-7			CML-7			CML-7		
CML-3	0.196	0.202	CML-8	0.205	0.21	CML-3			CML-8			CML-8			CML-8			CML-8			CML-8		
CML-4	0.197	0.204	CML-9	0.199	0.206	CML-4			CML-9			CML-9			CML-9			CML-9			CML-9		
CML-5	0.192	0.196	CML-10	0.205	0.218	CML-5			CML-10			CML-10			CML-10			CML-10			CML-10		



Information On Above: ↓ Material:> Carbon Steel Surface Condition:> Painted / Coated Information On Above: ↓ Material:> Carbon Steel Surface Condition:> Painted / Coated
CML1-6 (SHELL)/ CML7-9 (ROOF)/ CML10-12 (FLOOR). RESULTS ARE RECORDED IN INCHES. CML1-6 (SHELL)/ CML7-9 (ROOF)/ CML10-12 (FLOOR). RESULTS ARE RECORDED IN INCHES.