

TRANSLATED FROM CHINESE

**CW6180B HORIZONTAL LATHE**

**CW6280B GAP-BED TYPE LATHE**

# **INSTRUCTION BOOK**

**(For Mechanical & Hydraulic Units)**

**SHENYANG NO. 1 MACHINE TOOL WORKS  
THE PEOPLE'S REPUBLIC OF CHINA**

**Ver.1.0 / Dec., 2002**

20398

## CONTENTS

<b>1 MATTERS NEEDING APPLICATION TO SAFETY PROTECTION.....</b>	<b>5</b>
1.1 Electrical Shock Danger .....	5
1.2 Danger Resulting from Extrusion, Twine and Throw-off.....	5
1.3 Danger Resulting from Cutting, Scalding and Slipping .....	6
1.4 Miscellaneous .....	6
<b>2 MAIN APPLICATIONS OF THE MACHINE.....</b>	<b>7</b>
<b>3 SPECIFICATIONS OF THE MACHINE .....</b>	<b>8</b>
3.1 Main Specifications .....	8
3.2 Spindle .....	8
3.3 Feed System .....	8
3.4 Carriage .....	9
3.5 Tailstock .....	9
3.6 Power System.....	9
3.7 Cooling System.....	9
3.8 Controls and Lubricating System.....	10
3.9 Accessories .....	10
3.10 Overall Dimensions and Weights of the Machines .....	10
<b>4 HANDLING, INSTALLATION AND TRIAL RUNNING .....</b>	<b>11</b>
4.1 Handling .....	11
4.2 Installation.....	11
4.3 Cleaning and Trial Running .....	11
<b>5 CONTROLLING SYSTEM AND HYDRAULIC SYSTEM.....</b>	<b>21</b>
5.1 Arrangement Drawing of Control Levers for the Machine with Center Distance of 1.5m and 3m .....	21
5.2 Arrangement Drawing of Control Levers for the Mach. with Center Distance of 4m and more than 4m .....	23
5.3 Description of Hydraulic System .....	25
5.3.1 Description of Hydraulic System for the Machine of 1.5m and 3m .....	25
5.3.2 Description of Hydraulic System of the Machine with Size of 4m and more than 4m .....	27
<b>6 DRIVING SYSTEM AND BEARINGS .....</b>	<b>30</b>
<b>7 SETTING UP OF THE MACHINE .....</b>	<b>36</b>
7.1 Setting up of Feed System .....	38
7.2 For Cutting Special Threads by Means of Change Gears .....	39
7.3 For Cutting Inch Threads of 19 t.p.i .....	39
7.4 For Fine Feeds.....	39
7.5 For Broaching Oil Groove or Keyways with Carriage .....	39
7.6 Turning tapers .....	40
<b>8 ADJUSTMENT AND LUBRICATION OF THE MACHINE .....</b>	<b>41</b>
8.1 Adjustment of the Spindle Bearings .....	41
8.2 Adjustment of Safety Device in the Apron.....	42
8.3 Adjustment of the Backlash Between the Cross Slide Leadscrew and Nut.....	42

8.4 Lubrication of the Machine.....	44
<b>9 WEARING PARTS.....</b>	<b>45</b>