

**Howa**

**KIWAMI** series

**MQN-200V  $\alpha$**

**INSTRUCTION MANUAL**

**OPERATION MANUAL**



**HOWA MACHINERY, LTD.**

	PAGE
1. INTRODUCTION .....	1-1
2. SAFETY INSTRUCTIONS .....	2-1
3. SPECIFICATIONS OF MACHINE AND CNC .....	3-1
3-1 Standard specification of machine .....	3-1
3-2 Specification of CNC unit .....	3-2
3-3 M code list .....	3-3
3-4 G code list .....	3-4
3-5 Overall view .....	3-6
3-6 Strokes .....	3-7
3-7 Jig design reference .....	3-8
3-7-1 Interference .....	3-8
3-7-2 Details of the table .....	3-9
4. ENVIRONMENT, TRANSFER, and INSTALLATION .....	4-1
4-1 Working environment .....	4-1
(1) Place of installation .....	4-1
(2) Power supply .....	4-1
4-2 Lifting of machine .....	4-1
Fig.4-1 Machining center transfer work .....	4-2
Fig.4-2 Mounting fixing bracket .....	4-3
4-3 Installation .....	4-4
Fig.4-3 Connecting point of air-source .....	4-5
5. INSPECTIONS BEFORE TEST RUN .....	5-1
6. OPERATION .....	6-1
6-1 Function of operating parts .....	6-1
Fig.6-1 Layout of operator's panel .....	6-1
6-1-2 Optional switch / Indicator lamp .....	6-7
6-1-3 Toggle switch / Software switch .....	6-8
6-2 Preparation for operation .....	6-12
6-3 Manual operation .....	6-12
6-4 MDI operation .....	6-12
6-5 ATC sequence .....	6-13
6-6 Automatic operation .....	6-14

6-7 Handle operation .....	6-14
6-8 Routine operation procedure .....	6-16
6-9 Setting-up the tool .....	6-16
6-9-1 Attaching and detaching the tool .....	6-16
6-9-2 Tool offset .....	6-17
6-9-3 Boring shift direction setting .....	6-18
6-9-4 Restoration measures for POWER OFF and EMERGENCY STOP during ATC .....	6-19
6-9-5 Description of display PLC-I/F .....	6-20
(1) Display PLC-I/F screen .....	6-20
(2) Display of PLC device data .....	6-20
(3) Device data .....	6-20
(4) How to turn the ALARM lamp .....	6-22
(5) In case ATC cannot be returned to home position .....	6-23
 7. INTERLOCK .....	7-1
7-1 Axis movement .....	7-1
7-2 Spindle orientation .....	7-1
7-3 ATC operation (M6) .....	7-1
7-4 Magazine index by T-command .....	7-1
7-5 Automatic operation .....	7-1
 8. PROGRAMMING AND PROGRAM TRYOUT .....	8-1
8-1 Introduction .....	8-1
8-2 Setup before machining .....	8-1
8-3 Program registration and program running .....	8-3
8-3-1 New program registration .....	8-3
8-3-2 MDI data memory registration .....	8-3
8-3-3 Editing of program .....	8-4
8-3-4 Memory operation .....	8-4
8-4 Example of machining program .....	8-5
A. Example of program using tool length compensation and canned cycle .....	8-5
B. Example of program for cutter radius compensation .....	8-7
8-5 Basic program for others .....	8-9
 9. COOLANT UNIT (standard accessory) AND REMOVAL OF CHIPS .....	9-1