

SIEMENS

**SINUMERIK 840D/810D/FM-NC
Fundamentals**

Programming Guide

04.2000 Edition

User Documentation

SIEMENS

SINUMERIK 840D/840Di/810D/FM-NC Fundamentals

Programming Guide

Valid for

Control	Software Version
SINUMERIK 840D	5
SINUMERIK 840Di	5
SINUMERIK 840DE (Export version)	5
SINUMERIK 810D	3
SINUMERIK 810DE (Export version)	3
SINUMERIK FM-NC	3

Fundamental Geometrical Principles	1
Fundamental Principles of NC Programming	2
Positional Data	3
Programming Motion Commands	4
Path Action	5
Frames	6
Feedrate Control and Spindle Motion	7
Tool Offsets	8
Special Functions	9
Arithmetic Parameters and Program Jumps	10
Subprograms and Repetition of Program Sections	11
Tables	12
Appendix	A

Contents

Fundamental Geometrical Principles	1-19
1.1 Description of workpiece points	1-20
1.1.1 Workpiece coordinate systems	1-20
1.1.2 Definition of workpiece positions	1-21
1.1.3 Polar coordinates.....	1-23
1.1.4 Absolute dimension	1-24
1.1.5 Incremental dimension	1-25
1.1.6 Plane designations	1-26
1.2 Position of zero points	1-27
1.3 Position of coordinate systems.....	1-27
1.3.1 Overview of various coordinate systems.....	1-27
1.3.2 Machine coordinate system.....	1-29
1.3.3 Basic coordinate system.....	1-31
1.3.4 Workpiece coordinate system	1-32
1.3.5 Frame system.....	1-32
1.3.6 Assignment of workpiece coordinate system to machine axes.....	1-34
1.3.7 Current workpiece coordinate system	1-34
1.4 Axes.....	1-35
1.4.1 Main axes/Geometry axes.....	1-36
1.4.2 Special axes	1-37
1.4.3 Main spindle, master spindle	1-37
1.4.4 Machine axes	1-37
1.4.5 Channel axes	1-37
1.4.6 Path axes.....	1-38
1.4.7 Positioning axes	1-38
1.4.8 Synchronized axes	1-40
1.4.9 Command axes	1-40
1.4.10 PLC axes	1-40
1.4.11 Link axes (SW 5 and later).....	1-41
1.5 Coordinate systems and workpiece machining	1-43
Fundamental Principles of NC Programming	2-45
2.1 Structure and contents of an NC program.....	2-46
2.2 Language elements of the programming language.....	2-47
2.3 Programming a sample workpiece	2-69
2.4 First programming example for milling application	2-71
2.5 Second programming example for milling application	2-72

2.6 Programming example for turning application	2-75
---	------

Positional Data 3-77

3.1 General information	3-78
3.2 Absolute/incremental dimensions, G90/G91	3-79
3.2.1 G91 extension (SW 4.3 and higher)	3-82
3.3 Absolute dimensions for rotary axes, DC, ACP, ACN	3-83
3.4 Metric/imperial dimensions, G70/G71/G700/G710	3-85
3.5 Settable zero offset/frame, G54 to G599	3-88
3.6 Selecting the working plane, G17 to G19	3-92
3.7 Programmable working area limitation, G25/G26.....	3-94
3.8 Reference point approach, G74.....	3-97

Programming Motion Commands 4-99

4.1 General information	4-100
4.2 Traversing commands with polar coordinates, G110, G111, G112, AP, RP	4-102
4.3 Rapid traverse movement, G0.....	4-106
4.4 Linear interpolation, G1.....	4-108
4.5 Circular interpolation, G2/G3, CIP	4-111
4.6 Helical interpolation, G2/G3, TURN	4-124
4.7 Contour definitions	4-126
4.7.1 Straight line with angle	4-126
4.7.2 Two straight lines	4-127
4.7.3 Three straight lines	4-128
4.7.4 End point programming with an angle	4-129
4.8 Thread cutting with constant lead, G33	4-130
4.8.1 Programmable run-in and run-out path (SW 5 and later)	4-135
4.9 Rigid tapping, G331, G332	4-137
4.10 Tapping with compensating chuck.....	4-139
4.11 Stop during thread cutting.....	4-140
4.12 Approaching a fixed point, G75.....	4-143
4.13 Travel to fixed stop.....	4-145
4.14 Special turning functions	4-149
4.14.1 Position of workpiece	4-149
4.14.2 Dimensions for: radius, diameter	4-150

4.15 Chamfer, rounding.....	4-152
-----------------------------	-------

Path action	5-157
--------------------	--------------

5.1 Exact stop, G60, G9, G601, G602, G603.....	5-158
5.2 Continuous-path mode, G64, G641, G642, G643.....	5-160
5.3 Acceleration pattern, BRISK, SOFT, DRIVE	5-166
5.4 Overview of the various velocity controls.....	5-168
5.5 Traversing with feedforward control, FFWON, FFWOF	5-169
5.6 Programmable contour accuracy, CPRECON, CPRECOF	5-170
5.7 Dwell time, G4	5-171
5.8 Program sequence: Internal preprocessor stop	5-172

Frames	6-173
---------------	--------------

6.1 General	6-174
6.2 Frame instructions	6-175
6.3 Programmable zero offset	6-177
6.3.1 TRANS, ATRANS.....	6-177
6.3.2 G58, G59: Axial programmable ZO (SW 5 and later)	6-180
6.4 Programmable rotation, ROT, AROT	6-183
6.5 Programmable scale factor, SCALE, ASCALE.....	6-190
6.6 Programmable mirroring, MIRROR, AMIRROR.....	6-193
6.7 Frame generation according to tool orientation, TOFRAME	6-197
6.8 Deselecting the frame.....	6-198

Feedrate Control and Spindle Motion	7-199
--	--------------

7.1 Feedrate	7-200
7.2 Traverse positioning axes, POS, POSA, POSP	7-208
7.3 Position-controlled spindle operation, SPCON, SPCOF	7-211
7.4 Positioning spindles for position-controlled axis operation, SPOS, SPOSA.....	7-212
7.5 Milling on turned parts: TRANSMIT	7-217
7.6 Cylinder surface transformation: TRACYL	7-219
7.7 Feedrate for positioning axes and spindles	7-221
7.8 Percentage feedrate override, OVR, OVRA	7-224
7.9 Feedrate with handwheel override, FD, FDA.....	7-225

7.10 Percentage acceleration correction: ACC (Option).....	7-229
7.11 Feedrate optimization for curved path sections, CFTCP, CFC, CFIN	7-230
7.12 Spindle speed S, direction of spindle rotation M3, M4, M5.....	7-233
7.13 Constant cutting rate, G96, G97, LIMS.....	7-236
7.14 Constant grinding wheel peripheral speed, GWPSON, GWPSOF	7-238
7.15 Constant workpiece speed for centerless grinding, CLGON, CLGOF.....	7-241
7.16 Programmable spindle speed limitation, G25, G26	7-243
7.17 Several feedrates in one block: F, FMA.....	7-244
7.18 Blockwise feedrate: FB (as of SW 5.3).....	7-246

Tool Offsets 8-249

8.1 General information	8-250
8.2 List of tool types	8-253
8.3 Tool selection/tool call T	8-256
8.3.1 Tool change with M06 (mill).....	8-256
8.3.2 Tool change with T command (rotate).....	8-259
8.4 Tool offset D	8-260
8.5 Tool selection T with tool management	8-262
8.5.1 Turning machine with circular magazine	8-262
8.5.2 Milling machine with chain magazine.....	8-263
8.6 Tool offset call D with tool management.....	8-265
8.6.1 Turning machine with circular magazine	8-265
8.6.2 Milling machine with chain magazine.....	8-266
8.7 Make active tool offset operative immediately	8-267
8.8 Tool radius compensation, G40, G41, G42	8-268
8.9 Approach and retract from contour, NORM, KONT, G450, G451	8-275
8.10 Compensation at outside corners, G450, G451	8-278
8.11 Smooth approach and retraction	8-281
8.11.1 Extension approach and retract: G461/G462 (SW 5 and later).....	8-289
8.12 Collision monitoring, CDON, CDOF	8-293
8.13 2 1/2 D tool offset.....	8-295
8.14 Tool length offset for orientable tools: TCARR, TCOABS, TCOFR	8-297
8.15 Grinding-specific tool monitoring in part program TMON, TMOF	8-300

8.16 Additive offsets (SW 5 and higher)	8-302
8.16.1 Select offset (by DL number)	8-302
8.16.2 Define wear and setup values	8-303
8.16.3 Delete additive offsets (DELDL)	8-305
8.17 Tool offset – special features (SW 5 and higher)	8-306
8.17.1 Mirroring of tool lengths	8-307
8.17.2 Wear sign evaluation	8-307
8.17.3 Tool length and plane change	8-308
8.18 Tools with a relevant tool point direction (SW 5 and higher)	8-311
Special Functions	9-313
9.1 Auxiliary function outputs	9-314
9.1.1 M functions	9-319
9.1.2 H functions	9-322
Arithmetic Parameters and Program Jumps	10-323
10.1 Arithmetic parameters R	10-324
10.2 Unconditional program jumps	10-327
10.3 Conditional program jumps	10-329
Subprograms and Repetition of Program Sections	11-331
11.1 Use of subprograms	11-332
11.2 Subroutine call	11-335
11.3 Subprogram with program repetition	11-337
11.4 Program section repetition (SW 4.3 and later)	11-338
Tables	12-347
12.1 List of statements	12-348
12.2 List of addresses	12-363
12.2.1 Address letters	12-363
12.2.2 Fixed addresses	12-364
12.2.3 Fixed addresses with axis extension	12-365
12.2.4 Settable addresses	12-367
12.3 List of G functions/preparatory functions	12-371
12.4 List of predefined subprograms	12-380
12.4.1 Predefined subprogram calls	12-381
12.4.2 Predefined subprogram calls in motion-synchronous actions	12-391
12.4.3 Predefined functions	12-392
12.4.4 Data types	12-395

Appendix**A-397**

A Abbreviations	A-399
B Terms.....	A-407
C References.....	A-433
D Index	A-445
E Commands, Identifiers.....	A-453