

CNC SYSTEMS

OSP5020L OSP5000L-G

LS30-N, LH35-N, LH55-N Series CNC Lathes

MAINTENANCE MANUAL (5th Edition)

TABLE OF CONTENTS

	<u>PAGE</u>
SECTION 1 SPECIAL FEATURES OF OSP5020/OSP5000 SERIES	1
SECTION 2 SUMMARY OF OPERATION	2
SECTION 3 STRUCTURE OF OSP5020L/OSP5000L-G	3
1. CPU and Power Supply Unit	3
2. Servo Drive Unit	3
3. Relay and Magnet Switch Circuits	3
4. Spindle Drive Motor Control	4
5. Control Enclosure	4
6. Operation Panel	4
7. Absolute Position Feedback Encoders	4
8. Cooling Unit	4
SECTION 4 MAINTENANCE AND INSPECTION	5
1. Inspection during Installation	5
1-1. Installation Site	5
1-2. Environmental Requirements	5
1-3. Power Supply Voltage Inspection	6
2. Periodical Inspection	6
3. Operation and Structure of the NC	7
3-1. Example of Operation	7
3-2. Description on Each Major NC Unit	8
4. Self-Diagnostics	11
4-1. Alarm Display and Error Display	11
4-2. Check Data Display	11

	<u>PAGE</u>
SECTION 5 TROUBLE AND TROUBLESHOOTING	30
1. Analysis of Trouble	31
2. Machine-Mounted Electricals	32
2-1. Inspection of Limit Switches (Check Method by Multi-Meter)	33
2-2. Inspection of Rotary Switch for Turret Index (Testing by Self-Diagnostic Function)	34
3. Inspection of Position Encoder	35
4. Check Panel	36
5. CPU	36
5-1. Operation and Structure of the CPU	36
5-2. Checking CPU Operations	38
5-3. Loading Control Software through Floppy Disk	39
5-4. CPU Power Supply	42
6. Relay and Magnet Switch Circuits	44
6-1. Operation and Structure of a Relay and Magnet Switch Circuit	44
6-2. Inspection of Relays and Magnet Contactors	45
SECTION 6 BRUSHLESS SERVOMOTOR DRIVE UNIT (BL-D**A Series)	48
1. Configuration of BL-D**A	48
2. Construction	49
3. Protection and Alarm Monitoring Function	51
4. Trouble and Troubleshooting	53
5. Checking Power Transistor	58
SECTION 7 SPINDEL DRIVE UNIT FOR DC MOTOR - SDU-600 W SERIES	59
1. Overview	59
2. Alarm Conditions and Display of SDU-600 W Series Unit	62
2-1. Alarm Display and Details	62
2-2. Resetting of Alarm condition, Replacement of Blown Fuses and Resetting of No-Fuse Circuit Breaker	64
3. Construction of SDU-600 W Series Spindle Drive Unit	66
3-1. Layout of Component Parts	66
3-2. Principle Functions	68

	<u>PAGE</u>
4. Spare and Replacement Parts	69
4-1. Spare and Replacement Parts of SDU-600 W	69
4-2. Spare and Replacement Parts for DC Motors and Tachogenerators	70
5. Inspection and Maintenance of DC Motors and Tachogenerators	71
5-1. Inspection and Maintenance of Brushes	71
5-2. Inspection and Maintenance of Bearings	71
5-3. Inspection and Maintenance of Air Filter	71
6. Troubleshooting Chart	72
SECTION 8 SPINDLE DRIVE UNIT FOR VAC MOTOR (OKUMA MAKE)	73
1. Outline	73
2. VAC Drive Unit Construction	73
3. Operation Status Indication	78
3-1. Control PCB Operation Status Indicating Lamps	78
3-2. Operation Status Indicating Lamps	79
4. Troubleshooting	90
4-1. Confirmation of Power Supply, Connectors and Signals	90
4-2. Trouble and Troubleshooting	90
4-3. Recovery from Failure Status	99
5. Fuse Replacement	100
6. Inspection and Maintenance	104
7. Input/Output Signal Table	106
SECTION 9 COOLING UNIT	108
1. Maintenance and Inspection	108
SECTION 10 ELECTRICAL SPARE PARTS LIST	109
SECTION 11 POWER REQUIREMENTS	113

PAGE

APPENDED FIGURES

Layout Diagrams of Machine-mounted Electricals	116
Operation Panel	119
Internal Layouts of CNC Unit	120
PCB Type Relay Board Parts Arrangement Drawings	123