

CNC SYSTEM FOR MACHINING CENTERS YASNAC J300M/J100M PROGRAMMING MANUAL

Upon receipt of the product and prior to initial operation, read these instructions thoroughly, and retain for future reference.

REFERENCE

YASNAC J300M/J100M OPERATING MANUAL

TOE-C844-2.1

YASNAC J300M LARGE-CAPACITY PROGRAM OPERATING MANUAL TOE-C844-2.1-1



CONTENTS

Safety Information	iii
Visual Aids	iv
About this Manual	viii
Related Manuals	viii
NOTES FOR SAFE OPERATION	x

1 PROGRAMMING BASICS

1.1 FUNDAMENTALS OF PROGRAMMING TERMINOLOGY	1 - 2
1.1.1 Numerically Controlled Axes and the Number of Simultaneously Controllable Axes	1 - 2
1.1.2 Least Input Increment and Least Output Increment	1 - 7
1.1.3 Maximum Programmable Values for Axis Movement	1 - 9
1.1.4 Tape Format	1 - 10
1.1.5 Program Format	1 - 13
1.1.6 Optional Block Skip (/1), (/2 to /9) *	1 - 24
1.1.7 Buffer Register and Multi-active Register	1 - 25
1.2 BASICS OF FEED FUNCTION	1 - 26
1.2.1 Rapid Traverse	1 - 26
1.2.2 Cutting Feed (F Command)	1 - 27
1.2.3 F1-Digit Feed *	1 - 31
1.2.4 Feed per Minute Function (G94)	1 - 32
1.2.5 Solid Tap Mode (G93, G94) *	1 - 33
1.2.6 Automatic Acceleration and Deceleration	1 - 34

2 COMMANDS CALLING AXIS MOVEMENTS

2.1 INTERPOLATION COMMANDS	2 - 2
2.1.1 Positioning (G00, G06, G60)	2 - 2
2.1.2 Linear Interpolation (G01)	2 - 5
2.1.3 Circular Interpolation (G02, G03)	2 - 7
2.1.4 Helical Interpolation (G02, G03)*	2 - 14
2.2 REFERENCE POINT RETURN	2 - 16
2.2.1 Automatic Return to Reference Point (G28)	2 - 16
2.2.2 Reference Point Return Check (G27)	2 - 22
2.2.3 Return from Reference Point Return (G29)	2 - 24
2.2.4 Second to Fourth Reference Point Return (G30)	2 - 28

3 MOVEMENT CONTROL COMMANDS

3.1	SETTING THE COORDINATE SYSTEM	3 - 3
3.1.1	Selecting the Coordinate System	3 - 3
3.1.2	Base Coordinate System (G92)	3 - 3
3.1.3	Workpiece Coordinate System (G54 to G59)*	3 - 5
3.1.4	Local Coordinate System (G52 Q2)*	3 - 14
3.1.5	Machine Coordinate System (G53)	3 - 15
3.1.6	Rotation of Coordinate System (G68, G69)*	3 - 18
3.1.7	Plane Selection (G17, G18, G19)	3 - 21
3.2	DETERMINING THE COORDINATE VALUE INPUT MODES	3 - 22
3.2.1	Absolute/Incremental Designation (G90, G91)	3 - 22
3.2.2	Inch/Metric Input Designation (G20, G21)*	3 - 24
3.2.3	Scaling (G50, G51) *	3 - 26
3.3	TIME-CONTROLLING COMMANDS	3 - 31
3.3.1	Dwell (G04)	3 - 31
3.3.2	Exact Stop (G09)	3 - 31
3.3.3	Exact Stop Mode (G61, G64)	3 - 32
3.4	TOOL OFFSET FUNCTIONS	3 - 33
3.4.1	Tool Offset Data Memory	3 - 33
3.4.2	Tool Length Offset (G43, G44, G49)	3 - 34
3.4.3	Tool Position Offset (G45 to G48)	3 - 38
3.4.4	Tool Radius Offset C Function (G40, G41, G42) *	3 - 48
3.4.5	3-Dimensional Tool Offset Function (G40, G41, G42)*	3 - 90
3.5	S, T, M, AND B FUNCTIONS	3 - 98
3.5.1	Spindle Function (S Function)	3 - 98
3.5.2	Tool Function (T Function)	3 - 99
3.5.3	Miscellaneous Function (M Function)	3 - 100
3.5.4	Second Miscellaneous Function (B Function) *	3 - 102

4 ENHANCED LEVEL COMMANDS

4.1	PROGRAM SUPPORT FUNCTIONS (1)	4 - 3
4.1.1	Canned Cycles (G73 to G89, G181 to G189) *	4 - 3
4.1.2	Hole Machining Pattern Cycles (G70, G71, G72) *	4 - 34
4.1.3	Solid Tap Function (G84, G74) *	4 - 39
4.1.4	Deep-hole Solid Tap Function (G184, G174)*	4 - 50
4.1.5	Circle Cutting (G12, G13) *	4 - 64
4.1.6	Mirror Image ON/OFF (M94, M95) *	4 - 70
4.1.7	Programmable Data Input (G10) *	4 - 76
4.1.8	Subprogram Call Up Function (M98, M99)	4 - 79
4.1.9	Polar Coordinate Interpolation (G126, G127)*	4 - 81
4.1.10	Cylindrical Interpolation (G128, G129)*	4 - 91
4.2	PROGRAM SUPPORT FUNCTIONS (2)	4 - 101
4.2.1	Program Copy (G25)*	4 - 101
4.2.2	Automatic Corner Override (G106) *	4 - 104
4.2.3	Stored Stroke Limit B and C (G22, G23) *	4 - 109
4.2.4	Comment Output Function (M191) *	4 - 115
4.2.5	High-speed Cutting *	4 - 116
4.2.6	Chamfering and Corner Rounding Commands*	4 - 121
4.2.7	Corner Feedrate Designation (G107, G108)*	4 - 126
4.3	AUTOMATING SUPPORT FUNCTIONS	4 - 138
4.3.1	Skip Function (G31) *	4 - 138
4.3.2	Program Interrupt Function (M90, M91) *	4 - 141
4.3.3	Tool Life Control Function *	4 - 144
4.4	MACROPROGRAMS	4 - 154
4.4.1	Differences from Subprograms	4 - 154
4.4.2	Macroprogram Call (G65, G66, G67)	4 - 156
4.4.3	Variables	4 - 169
4.4.4	Operation Instructions	4 - 201
4.4.5	Control Instructions	4 - 203
4.4.6	Registering the Macroprogram	4 - 209
4.4.7	RS-232C Data Output 2 (BPRNT, DPRNT)	4 - 210
4.4.8	Macroprogram Alarm Numbers	4 - 214
4.4.9	Examples of Macroprograms	4 - 215

Appendix 1 G CODE TABLE

APPENDIX 1.1	G CODE TABLE	A1 - 2
--------------	--------------	--------