

A large, stylized white graphic on an orange background, resembling a stylized 'M' or a series of overlapping curved lines.

Mazak

**OPERATING MANUAL
QUICK TURN SMART 200
QUICK TURN SMART 250
QUICK TURN SMART 200M
QUICK TURN SMART 250M**

MANUAL No. : HB07SA0024E
NC Unit : MAZATROL SMART

OPERATING MANUAL



OPERATING MANUAL

QUICK TURN SMART 200

QUICK TURN SMART 250

QUICK TURN SMART 200M

QUICK TURN SMART 250M

MANUAL No. : HB07SA0024E

NC Unit : MAZATROL SMART

Before using this machine and equipment, fully understand the contents of this manual to ensure proper operation. Should any questions arise, please ask the nearest Technical Center or Technology Center.

IMPORTANT NOTICE

1. Be sure to observe the safety precautions described in this manual and the contents of the safety plates on the machine and equipment. Failure may cause serious personal injury or material damage. Please replace any missing safety plates as soon as possible.
2. No modifications are to be performed that will affect operation safety. If such modifications are required, please contact the nearest Technical Center or Technology Center.
3. For the purpose of explaining the operation of the machine and equipment, some illustrations may not include safety features such as covers, doors, etc. Before operation, make sure all such items are in place.
4. This manual was considered complete and accurate at the time of publication, however, due to our desire to constantly improve the quality and specification of all our products, it is subject to change or modification. If you have any questions, please contact the nearest Technical Center or Technology Center.
5. Always keep this manual near the machinery for immediate use.
6. If a new manual is required, please order from the nearest Technical Center or Technology Center with the manual No. or the machine name, serial No. and manual name.

Issued by *Manual Publication Section, Yamazaki Mazak Corporation, Japan*

CONTENTS

Page

1	INTRODUCTION	1-1
1-1	Machine Overview	1-1
1-1-1	Intended use of the machine	1-1
1-1-2	Operating position.....	1-1
1-1-3	Features.....	1-2
1-2	List of Manuals to Be Used.....	1-4
1-3	Numbering System for Pages.....	1-4
1-4	Numbering System for Figures and Tables	1-4
1-5	Distinction between Standard and Optional Specifications.....	1-5
1-6	Confirmation of Spindle Development-Wise Specifications	1-5
2	SAFETY PRECAUTIONS	2-1
2-1	Rule	2-1
2-2	Basic Safety Items.....	2-1
2-3	Clothing and Personal Safety	2-3
2-4	Safety Items Related to Operation	2-4
2-5	Safety Items Related to Gripping Workpiece and Tooling	2-6
2-6	Safety Items Related to Gripping Workpiece and Tooling (in Milling)	2-7
2-7	Safety Items Related to Maintenance.....	2-7
2-8	Safety Items Related to Workplace	2-8
2-9	Safety Items Related to Chip Conveyor.....	2-9
2-10	Safety Equipment	2-9

2-11	Remarks on the Cutting Conditions Recommended by the NC	2-9
2-12	Safety Nameplates	2-10
2-13	Location and Function of Safety Devices	2-15
3	OVERVIEW	3-1
3-1	Overview of Mechanisms	3-1
3-2	Overview of Control System	3-2
3-3	Disposition of Machine Components	3-4
3-4	Definition of Coordinate Axes	3-7
3-5	Milling Holder Configurations.....	3-8
3-5-1	H-type milling holder	3-8
3-5-2	V-type milling holder	3-9
4	OPERATING PANEL AND FUNCTIONS OF SWITCHES	4-1
4-1	Layout of Operating Panels	4-1
4-2	NC Operating Panel and Machine Operating Panel	4-2
4-2-1	Disposition of switches and lamps.....	4-2
4-2-2	Controls on the NC operating panel	4-3
4-2-3	Indicator lamps on the operating panel.....	4-5
4-2-4	Status indicator window	4-6
4-3	Machine Operating Panel	4-8
4-4	USB Interface I/O Panel	4-11
5	PREPARATION FOR OPERATION	5-1
5-1	Inspection at the Start of Operation	5-1

5-2	How to Stop the Machine	5-3
5-2-1	How to stop the machine in emergencies	5-3
5-2-2	Other stopping methods	5-3
5-3	Procedure for Switching the Power ON	5-3
5-4	Inspection after Switching the Power ON	5-5
5-5	Switching the Power OFF	5-6
5-6	Zero-Point Return	5-6
5-6-1	Axis zero point return procedure	5-7
5-7	Warmup Operation	5-8
5-8	Opening the Machine Door	5-9
5-9	Opening/Closing of Chuck	5-9
6	MANUAL OPERATION	6-1
6-1	Manual Operation Modes	6-1
6-1-1	Selecting a manual operation mode	6-1
6-2	Spindle Operation	6-1
6-2-1	Spindle start	6-2
6-2-2	Spindle stop	6-3
6-2-3	Spindle jog	6-3
6-3	C-Axis Operation	6-4
6-3-1	C-axis rapid feed	6-4
6-3-2	C-axis cutting feed	6-5
6-3-3	C-axis manual pulse feed	6-6
6-4	X-Axis, Z-Axis and W-(Tailstock) Axis Feed Operation	6-8

6-4-1	Rapid feed	6-9
6-4-2	Cutting feed	6-10
6-4-3	Pulse feed	6-11
6-4-4	Barrier cancel.....	6-13
6-5	Tool Selection.....	6-14
6-5-1	Rotation of turret	6-14
6-5-2	Milling spindle operation	6-16
6-6	Tailstock Operation.....	6-18
6-6-1	Display and selection of tailstock thrust.....	6-18
6-6-2	Moving the tailstock	6-19
6-7	Operation of the Steady Rest	6-21
6-7-1	Movement of the steady rest	6-21
6-7-2	Clamping/Unclamping of the steady rest.....	6-22
6-7-3	Status display window for steady rest.....	6-23
6-8	Other Manual Operations	6-24
6-8-1	Soft limit and its release.....	6-24
6-8-2	Machine lock.....	6-25
6-8-3	WORK LIGHT and COOLANT MANUAL.....	6-25
6-8-4	Machine set up switch	6-26
6-8-5	Manual operation of parts catcher (Option)	6-27
6-8-6	Operator door automatic opening/closing device (Option).....	6-28
7	PREPARATION FOR MACHINING	7-1
7-1	Mounting of Tools	7-1
7-1-1	Mounting/removal of tool holder and tools QT-Smart200/250	7-1

7-1-2	Mounting/removal of tool holder and tools QT-Smart200M/250M	7-5
7-1-3	Heavy tool layout	7-21
7-2	Mounting Direction of Tool Holding Block	7-23
7-3	Preparation for Gripping Workpiece (Soft Jaw Machining)	7-24
7-3-1	In the case of workpiece external gripping	7-24
7-3-2	In the case of workpiece internal gripping	7-26
7-3-3	Setting spindle speed when using special jaw	7-27
7-4	Notes on the Diameter Turned	7-30
7-4-1	For a diameter turned up to 150 mm (5.91 in)	7-30
7-4-2	For a diameter turned over 150 mm (5.91 in)	7-30
7-4-3	In case of using the steady rest	7-30
7-5	Useful Information for Using the Tailstock	7-31
7-5-1	Method of pressing the workpiece (Normal pressing)	7-31
7-5-2	Method of pressing the workpiece (Low thrust pressing)	7-37
7-5-3	Changing the thrust	7-38
7-5-4	M code related to tailstock operation	7-40
7-5-5	Precautions for using the tailstock	7-41
7-6	Automatic Operation of the Steady Rest	7-41
7-7	Energy Saving Mode	7-43
7-7-1	Reduction in stand-by power consumption	7-43
7-7-2	Setting the timers for the automatic deactivation	7-44
8	AUTOMATIC OPERATION	8-1
8-1	Automatic Operation Execution	8-1
8-1-1	Automatic operation execution procedure	8-1

8-1-2	Types of automatic operation mode	8-3
8-2	Selecting Execution Conditions	8-19
8-2-1	Optional stop.....	8-20
8-2-2	Dry run	8-21
8-2-3	Machine lock.....	8-23
8-2-4	Work light.....	8-23
8-2-5	Barrier cancel.....	8-24
8-2-6	Block skip.....	8-24
8-2-7	Single block	8-25
8-2-8	Comparison stop.....	8-26
8-2-9	Threading position teach (Option)	8-29
8-3	Changing the Cutting Conditions	8-32
8-3-1	Rapid traverse override	8-32
8-3-2	Cutting feed override	8-33
8-3-3	Spindle/Milling-spindle speed override	8-34
8-3-4	VFC function	8-35
8-4	Stopping Automatic Operation.....	8-38
8-4-1	Emergency stop.....	8-39
8-4-2	Reset	8-40
8-4-3	Feed hold.....	8-40
8-4-4	Stopping by changeover to a manual operation mode	8-41
8-4-5	Single-block stop	8-42
8-4-6	Program stop	8-42
8-4-7	Stopping by turning the power OFF	8-43

8-5	Manual Interruption.....	8-44
8-5-1	Manual pulse handle interruption.....	8-44
8-5-2	TPS function	8-45
8-6	Operations Possible during Automatic Operation	8-48
8-6-1	Data rewriting.....	8-48
8-7	Completion of Operation.....	8-50
8-7-1	Procedure for switching the power OFF	8-50
8-7-2	Cleaning and inspections on completion of operation	8-50
9	STANDARD SPECIFICATION OF THE MACHINE.....	9-1
9-1	Principal Specification	9-1
9-2	Spindle Nose Diagram.....	9-8
9-3	Characteristics of Turning Spindle Motor.....	9-10
9-3-1	QT-Smart200: Standard specifications (15.0 kW)	9-10
9-3-2	18.5 kW QT-Smart200 (Optional specifications)/200M (Standard specifications)	9-10
9-3-3	18.5 kW QT-Smart250/250M (Standard specifications)	9-11
9-3-4	QT-Smart250/250M: Standard specifications (26.0 kW)	9-11
9-4	Characteristics of Milling Spindle Motor (QT-Smart200M/250M).....	9-12
9-4-1	4500 min ⁻¹	9-12
9-4-2	6000 min ⁻¹ (Option)	9-12
9-5	Stroke Diagram	9-14
9-6	Tooling Interference Diagram	9-62
9-7	Tooling System Diagram	9-90

9-8 Relation Diagram between Chuck and TOOL EYE9-106

4-

00-

0

00-