

# HORIZONTAL MACHINING CENTER

# A55

**Version D**

# OPERATION MANUAL



## **WARNING**

1. Do not operate, maintain, or inspect the machine before you read intensively and understand this Instruction Manual.
2. Store this Instruction Manual with care so that you can consult it as necessary in performing operation, maintenance or inspection of the machine.



# **OPERATION**

# 1 OPERATION OF MACHINE

- 1.1 Safety Information
- 1.2 Operation Procedure
- 1.3 Manual Operation
- 1.4 Automatic Operation
- 1.5 Program Registration and Editing
- 1.6 Other Operations of NC Screens
- 1.7 PC Screens and Operation

# 2 MACHINING OPERATION

- 2.1 Safety Precautions on Operation
- 2.2 Disposal of Chips, Waste Solution, and Filters
- 2.3 Machining Procedure
- 2.4 Simple Machining Examples
- 2.5 Machining including ATC
- 2.6 Machining including B-Axis Indexing
- 2.7 Machining including Pallet Change
- 2.8 Machining using the Monitoring Function
- 2.9 Random Operation

# Contents

1.1	Safety Information .....	1.1- 1
1.1.1	Safety information on operation .....	1.1- 1
1.1.2	Safety devices .....	1.1- 3
1.2	Operation Procedure .....	1.2- 1
1.2.1	Checking at the start of work .....	1.2- 1
1.2.2	Turning ON the power supply .....	1.2- 2
1.2.3	Operation of the machine .....	1.2- 3
1.2.4	Turning OFF the power supply .....	1.2- 4
1.3	Manual Operation .....	1.3- 1
1.3.1	Manual reference point return .....	1.3- 1
1.3.2	Rapid traverse .....	1.3- 5
1.3.3	Jog feed (manual cutting feed) .....	1.3- 10
1.3.4	Handle feed .....	1.3- 12
1.4	Automatic Operation .....	1.4- 1
1.4.1	MDI mode .....	1.4- 3
1.4.2	Preparation for memory operation (1) Making and entering a program .....	1.4- 12
1.4.3	Preparation for memory operation (2) Setting a work coordinate system .....	1.4- 16
1.4.4	Automatic operation in the memory mode .....	1.4- 18
1.4.5	Memory operation using various functions .....	1.4- 21
1.4.6	Automatic operation in the tape mode .....	1.4- 25

1.5	Program Registration and Editing .....	1.5-
1.5.1	Registering programs from NC tape to memory .....	1.5-2
1.5.2	Editing a program .....	1.5-8
1.5.3	Registering a program to memory using FDD .....	1.5-1
1.5.4	RS232C and baud rate .....	1.5-1
1.5.5	Punching out a program .....	1.5-2
1.5.6	Background editing of a program .....	1.5-2
1.6	Other Operations of NC Screens .....	1.6-1
1.6.1	Entering a tool offset .....	1.6-1
1.6.2	Entering a setting value in work coordinate system .....	1.6-5
1.6.3	Display and resetting of NC alarms .....	1.6-1
1.6.4	Input and change of setting data .....	1.6-1
1.6.5	Input and change of NC parameters .....	1.6-1
1.7	PC Screens and Operation .....	1.7-1
1.7.1	Primary Operation screen .....	1.7-2
1.7.2	Alarm screen .....	1.7-5
1.7.3	Parameter screen .....	1.7-7
1.7.4	Regular Maintenance screen .....	1.7-1



## 2 MACHINING OPERATION

2.1	Safety Precautions on Operation .....	2.1- 1
2.1.1	Setup work .....	2.1- 1
2.1.2	Machining operation .....	2.1-2
2.2	Disposal of Chips, Waste Solution, and Filters .....	2.2-1
2.3	Machining Procedure .....	2.3-1
2.4	Simple Machining Examples .....	2.4-1
2.4.1	Machining drawings and setup work .....	2.4-1
2.4.2	Plane cutting with a face mill .....	2.4-12
2.4.3	Side cutting with an end mill .....	2.4-24
2.4.4	Pocket cutting with an end mill .....	2.4-31
2.4.5	Drilling and tapping .....	2.4-36
2.4.6	Boring.....	2.4-45
2.5	Machining including ATC .....	2.5-1
2.5.1	Preparation for ATC .....	2.5-1
2.5.2	Tool calling and automatic tool change .....	2.5-10
2.5.3	ATC including tool length compensation .....	2.5-12
2.5.4	Actual machining including ATC .....	2.5-14
2.6	Machining including B-Axis Indexing.....	2.6-1
2.6.1	B-axis index command .....	2.6-1
2.6.2	Actual machining including B-axis indexing and ATC .....	2.6-2
2.7	Machining including Pallet Change .....	2.7-1
2.7.1	Pallet Change (PC) .....	2.7-1
2.7.2	Mounting a workpiece on the pallet on stocker side .....	2.7-3
2.7.3	Actual machining including PC, B-axis index, and ATC.....	2.7-4

2.8	Machining using the Monitoring Function.....	2.8-1
2.8.1	Machining using the SL function .....	2.8-1
2.8.2	Machining using the AC function .....	2.8-5
2.8.3	Machining using the TL function .....	2.8-8
2.8.4	Machining using spare tool change function .....	2.8-14
2.8.5	Machining using direct spare tool change function .....	2.8-19
2.9	Random Operation .....	2.9- 1
2.9.1	Mounting workpieces on the pallets .....	2.9- 1
2.9.2	Preparation (1)....Registering the programs .....	2.9- 2
2.9.3	Preparation (2)....Mounting the workpieces .....	2.9- 6
2.9.4	Starting the random operation .....	2.9- 8
2.9.5	Random operation using the block skip .....	2.9- 9