



# Contents

PGM Page

## Tangential contour approach and departure

Approach to and departure from a contour \_\_\_\_\_ 100 \_\_\_\_\_ 6

## Straight line milling with the vertical spindle

Cartesian coordinates \_\_\_\_\_ 110 \_\_\_\_\_ 10

Polar coordinates \_\_\_\_\_ 120 \_\_\_\_\_ 12

Chamfers \_\_\_\_\_ 130 \_\_\_\_\_ 14

D-straight line milling \_\_\_\_\_ 140 \_\_\_\_\_ 16

## Straight line milling with the horizontal spindle

End points in Cartesian coordinates \_\_\_\_\_ 150 \_\_\_\_\_ 18

End points in polar coordinates \_\_\_\_\_ 160 \_\_\_\_\_ 20

## Circular path milling with the vertical spindle

Rounding of corners \_\_\_\_\_ 210 \_\_\_\_\_ 24

Centre point and end point, End points in Cartesian coordinates \_\_\_\_\_ 220 \_\_\_\_\_ 26

Centre point and end point, End points in polar coordinates \_\_\_\_\_ 225 \_\_\_\_\_ 28

Radius and end point \_\_\_\_\_ 230 \_\_\_\_\_ 30

Tangential contour connection, End points in Cartesian coordinates \_\_\_\_\_ 240 \_\_\_\_\_ 32

Tangential contour connection, End points in polar coordinates \_\_\_\_\_ 245 \_\_\_\_\_ 34

## Circular path milling with the horizontal spindle

Rounding of corners \_\_\_\_\_ 250 \_\_\_\_\_ 36

Centre point and end point, End points in Cartesian coordinates \_\_\_\_\_ 260 \_\_\_\_\_ 38

Centre point and end point, End points in polar coordinates \_\_\_\_\_ 265 \_\_\_\_\_ 40

Radius and end point, End points in Cartesian coordinates \_\_\_\_\_ 270 \_\_\_\_\_ 42

Tangential contour connection, End points in Cartesian coordinates \_\_\_\_\_ 280 \_\_\_\_\_ 44

Tangential contour connection, End points in polar coordinates \_\_\_\_\_ 285 \_\_\_\_\_ 46

## Helical path milling

Using the vertical spindle, Programming via a CP-block \_\_\_\_\_ 310 \_\_\_\_\_ 50

Using the horizontal spindle, Programming via a CP-block \_\_\_\_\_ 320 \_\_\_\_\_ 52

Using the horizontal spindle and an NC-rotary table (C-axis) \_\_\_\_\_ 330 \_\_\_\_\_ 54

## Canned cycles

Peck drill \_\_\_\_\_ 410 \_\_\_\_\_ 58

Tapping \_\_\_\_\_ 420 \_\_\_\_\_ 62

Slot milling \_\_\_\_\_ 430 \_\_\_\_\_ 64

Rectangular pocket milling \_\_\_\_\_ 440 \_\_\_\_\_ 66

Circular pocket milling \_\_\_\_\_ 450 \_\_\_\_\_ 68

Variable contour pocket milling (example 1) \_\_\_\_\_ 460 \_\_\_\_\_ 70

Variable contour pocket milling (example 2) \_\_\_\_\_ 470 \_\_\_\_\_ 78

### Sub-programming

Tool change	510	86
Milling of a machining pattern	520	90
Milling a hexagonal die	530	92

### Coordinate transformations

Datum shift	610	96
Coordinate system rotation	620	100
Datum shift with subsequent rotation	630	102
Mirror imaging a contour	640	106
Reduction and enlargement of contours	650	110

### Variable parameter programming

Hole patterns on a pitch circle	710	114
Milling of a drawing die, Example of semi-cylinder	720	120
Milling of a drawing die, Example of a domed rectangular block	730	128

### Customized macros, program call

Peck drilling with chip-breaking - Main program	810	138
Peck drilling with chip-breaking - Cycle	9990	142
Stepover milling with peck movement - Main program	820	144
Stepover milling with peck movement - Cycle	9995	150