

PROGRAMMING

MAR. 1989
EDITION 0-1

CONTENTS

1. THE OUTLINE OF THE PROGRAMMING	1
1-1 Regular Procedure for Making Program	1
1-2 The Motion of the Turret Slide	2
1-3 The Cutting Area	2
1-4 Part Dimensioning	6
1-5 Part Layout Sheet	7
1-6 Process Sheet	9
2. TAPE INFORMATION	10
2-1 Move Command for the Cutting Tools	12
2-2 The Absolute and the Incremental Input	13
2-3 The Program Format	15
2-4 G-Function (Preparatory Function)	19
[1] G50 (Maximum spindle speed setting)	19
[2] G00 (Positioning)	20
[3] G01 (Linear interpolation, 45° Chamfering, Rounding)	21
[4] G02, G03 (Circular interpolation, Radius programming for circular interpolation)	27
[5] G04 (Dwell)	32
[6] G10 (Changing of tool offset amount programmable data input)	34
[7] G20, G21 (Inch/metric input)	35
[8] G25, G26 (Spindle speed fluctuation detecting function)	36
[9] G27 (Reference point return check)	37
[10] G28 (Automatic return to reference point)	38
[11] G30 (Second reference point return)	39
[12] G31 (Skip function)	40
[13] G32 (Thread cutting)	41
[14] Other G-codes	54
[15] List of G-codes and their group	56
2-5 F-Function (Feed Function)	58
[1] Feed rate per revolution of the spindle (G99)	58
[2] Feed rate per minute (G98)	59
2-6 S-Function (Spindle Speed Function)	61
[1] Spindle RPM direct command (G97 mode)	61
[2] Cutting speed command (G96 mode)	63
2-7 Coordinate System Setting	64
2-8 T-Function (Tool Function)	67
[1] Designation of tool selection/geometry offset (tool shape) number	67
[2] Tool offset (General)	68
[3] Tool position offset (Wear offset)	69
[4] Notes of T-function	73
[5] Tool nose radius compensation	73
2-9 M-Function (Miscellaneous Function)	74
2-10 Other Function	86
[1] '/' Block delete (Optional Block Skip)	86
3. EXAMPLE OF PROGRAMMING OF VARIOUS OPERATIONS	87
3-1 Facing Operation	87
3-2 Turning Operation	89
3-3 Drilling Operation	90
3-4 Boring Operation	91
3-5 Grooving Operation	92

3-6 Taper Cutting and Chamfering Operation	93
3-7 Radius Cutting Operation	94
3-8 Cutting off Operation	96
3-9 Bar Pull out Operation	98
3-10 Threading Operation	101
4. TOOL NOSE RADIUS COMPENSATION (G40 to G42)	103
4-1 Different Dimension by Tool Nose Radius	103
4-2 The Motion of Tool Nose Radius Compensation	105
4-3 Command of Tool Nose Radius Compensation	106
4-4 Prohibited command on the compensation	110
5. EXAMPLE OF PROGRAMMING	114
5-1 Part Dimensioning	114
5-2 Part Layout Sheet	115
5-3 Work Coordinate System Setting and Tool Selecting Position	116
5-4 Process Sheet	120
6. CANNED CYCLE	124
6-1 G90 (Turning Cycle)	124
6-2 G92 (Thread Cutting Cycle)	129
6-3 G94 (Facing Cycle)	135
7. MULTIPLE REPETITIVE CUTTING CYCLE	139
7-1 G71 (Stock Removal Cutting Cycle in Turning)	139
7-2 G72 (Stock Removal Cutting Cycle in Facing)	144
7-3 G73 (Pattern Repeated Cutting Cycle)	149
7-4 G70 (Finish Cutting Cycle)	153
7-5 G74 (Longitudinal Pecking Cycle)	154
7-6 G75 (Cross Pecking Cycle)	157
7-7 G76 (Thread Cutting Cycle)	160
7-8 Notes on Multiple Repetitive Cycles (G70 to G76)	166
8. DRAWING DIMENSION DIRECT INPUT (OPTION)	167
[1] Instruction method	168
[2] Commanding of angle, arc and chamfer	169
[3] Commands table	170
9. STANDARD PROGRAM STYLE	174
10. SAMPLE PROGRAMMING	179
CHUCK WORK	180
SHAFT WORK	185
BAR WORK	192
11. LIST OF TAPE FORMAT FOR LE-11 AND LE-21	199
11-1 Preparatory Function (G Function)	199
11-2 Miscellaneous Function (M Function)	201
11-3 Tool Function (T Function)	202
11-4 Spindle Function (S Function)	202
11-5 Multiple Repetitive Cycle	203
11-6 Canned Cycle	206