PROGRAMMING MANUAL

GLS-680H

CNC OPTICAL PROFILE GRINDER

with FANUC 15M-A

TECNO WASINO CO.,LTD.

GLS680HPR-0995-N

CONTENTS

Page

1. CNC UNIT SPECIFICATIONS 1

1-1 CNC unit specification 1
1-2 Standard CNC functions 2
1-3 Optional CNC functions 4

2. BASICS OF PROGRAMMING 5

2-1 Program construction 5
2-1-1 CNC programs 5
2-1-2 Program number 5
2-1-3 Sequence number 6
2-1-4 Word and address 7
2-1-5 Basic addresses and command ranges 8
2-2 CNC axes 9
2-2-1 Number of CNC axes 9
2-2-2 Minimum increments 9
2-3 Preparatory function (G-code) 10
2-3-1 Outline 10
2-3-2 G-code list 11
2-4 Interpolation function 14
2-4-1 Positioning (G00) 14
2-4-2 Linear interpolation (G01) 15
2-4-3 Circular interpolation (G02, G03) 17
2-5 Feed function 19
2-5-1 Rapid feed rate 19
2-5-2 Grinding feed rate 19
2-5-3 Exact stop 20
2-5-4 Dwell 21
2-6 Coordinate system 21
2-7 Dimension data 23
2-7-1 Absolute command and incremental command 23
2-7-2 Decimal point input 24

Page

2-8 Miscellaneous function (M-code) 27
2-8-1 Outline 27
2-8-2 Descriptions of M-codes for program control 27
2-8-3 M-code list 29
2-9 Quick-reference table for CNC unit operations 30

3. INTERACTIVE MACRO 33

3-1 Outline 33
3-1-1 Summary 33
3-1-2 System formation 33
3-2 Macro system menu screen 36
3-2-1 Screen display 36
3-2-2 Descriptions of software keys 36
3-3 Teaching-playback function 38
3-3-1 Outline 38
3-3-2 Teaching-playback screen 39
3-3-3 Descriptions of software keys 40
3-3-4 Summary of teaching-playback operation 41
3-3-5 Teaching-playback example (1) by wheelhead feed (X and Y) 43
3-3-6 Teaching-playback example (2) by wheelhead feed (X and Y) and swivel (C) 45
3-3-7 Notes for teaching operation 49
3-4 Taper interpolation function 51
3-4-1 Outline 51
3-4-2 Taper feed screen 51
3-4-3 Descriptions of software keys 52
3-4-4 Setting of taper feed angle 53
3-4-5 Setting of taper feed rate 54
3-4-6 Operation 55
3-4-7 Notes for taper feed operation 57
3-4-8 Example of taper feed operation 58
3-5 Simplified circular interpolation function 60
3-5-1 Outline 60
3-5-2 Circular arc feed screen 60
3-5-3 Descriptions of software keys 61
3-5-4 Three-point teaching 62

Page
3-5-5 Setting of arc feed rate 63
3-5-6 Operation 64
3-5-7 Notes for arc feed operation 65
3-6 Wheel swivel function 66
3-6-1 Outline 66
3-6-2 Wheel swivel setting screen 67
3-6-3 Descriptions of software keys 67
3-6-4 Teaching of three swivel positions 68
3-6-5 Setting of swiveling feed rate 70
3-6-6 Operation 71
3-6-7 Notes for wheel swivel operation 74
3-7 4-axis canned cycle function 76
3-7-1 Outline 76
3-7-2 4-axis canned cycle screens 77
3-7-3 Descriptions of software keys 79
3-7-4 Setting of 4-axis canned cycle 80
3-7-5 Notes for 4-axis canned cycle 88
3-7-6 Summary of 4-axis canned cycle operation 89
3-8 Machining time computation function (Optional) 91
3-8-1 Outline 91
3-8-2 Machining time computation screen 91
3-8-3 Descriptions of software keys 92
3-8-4 Operation procedure 93
3-8-5 Notes for machining time computation 97
3-9 Zero return function 98
3-9-1 Outline 98
3-9-2 Zero return setting 99
3-9-3 Notes for zero return function 99
3-10 Operator's panel 100
3-10-1 Outline 100
3-10-2 Operator's panel screen 100
3-10-3 Descriptions of software switches 101
3-10-4 Description of software key 102
3-11 Custom macro programs 103
3-11-1 Outline 103
3-11-2 Notes for custom macro programs 104
3-11-3 Macro system's custom macro programs 105

Page

4. PROGRAMMING EXAMPLES 108

4-1 Programming by teaching 108
4-1-1 Programming procedure 108
4-1-2 Teaching example 110
4-2 Program check and automatic operation by playback 113
4-2-1 Program checking procedure 113
4-2-2 Automatic grinding operation by playback 114
4-2-3 Notes for automatic operation 115
4-2-4 Notes for programs created by teaching 116
4-3 Programming of main programs and subprograms 117
4-3-1 Rough grinding cycle program 117
4-3-2 Pattern repeating cycle programs 120
4-4 Programming for indirect grinding 125
4-5 Various program examples 128
4-5-1 Linear feed grinding (in Y-axis, left side) 128
4-5-2 Linear feed grinding (in Y-axis, right side) 129
4-5-3 Linear feed grinding (in X-axis) 130
4-5-4 Taper feed grinding 131
4-5-5 Circular feed and linear feed grinding 132
4-5-6 Linear feed grinding (in X-axis, from midpoint) 133
4-5-7 Combined linear and circular grinding (1) 134
4-5-8 Combined linear and circular grinding (2) 135
4-5-9 Combined linear and circular grinding (3) 136
4-5-10 Combined linear and circular grinding (4) 137
4-5-11 Combined linear and circular grinding (5) 138
4-5-12 Rough grinding cycle by wheel position offset 139
4-5-13 Rough grinding cycle by wheel edge R offset 141
4-5-14 Grinding of the same figure 142

5. OPTIONAL FEATURES 143

5-1 Spindle speed direct command 143
5-1-1 Outline 143
5-1-2 Spindle speed data change 143
5-1-3 Operation 146
5-2 Retrace function 147

Page
5-3 Automatic feed rate control 148
5-3-1 Outline 148
5-3-2 Operation 148
5-3-3 Adjustment of sensor sensitivity 151
5-3-4 Setting of parameters 152
5-3-5 Notes for automatic feed rate control 152