

# ONE-TOUCH IGF-L

---


---

OSP7000L/700L

---

## OPERATION -APPLICATION- (3rd Edition)

Pub. No. 3868-E-R1 (LE32-035-R3) July 1995



# INTRODUCTION



All useful functions of the one-touch IGF are described in this manual.

The table of contents of this manual is itemized so that the user can use it like a dictionary, for example locating the necessary explanation from the table of contents on which names of functions, screens, or function keys are used.

Please make the most of this manual to use the one-touch IGF more effectively.

TABLE OF CONTENTS

|                                                                                                                                                                             | <u>PAGE</u> |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| PART I APPLICATION .....                                                                                                                                                    | 1           |
| SECTION 1 STARTING-UP ONE-TOUCH IGF SYSTEM .....                                                                                                                            | 1           |
| 1. Selection of One-touch IGF Mode .....                                                                                                                                    | 1           |
| 2. Turning On Graphic Edit Function .....                                                                                                                                   | 3           |
| SECTION 2 STANDARD HOLE DATA SETTING .....                                                                                                                                  | 6           |
| 1. What is the Function of Standard Hole Data Setting? .....                                                                                                                | 6           |
| 2. Standard Hole Data Setting Procedure .....                                                                                                                               | 8           |
| 3. Items to be Set as Standard Hole Data .....                                                                                                                              | 10          |
| SECTION 3 TOOL DATA SETTING .....                                                                                                                                           | 15          |
| 1. What is the Function of Tool Data Setting? .....                                                                                                                         | 15          |
| 2. Tool Data Setting Procedure .....                                                                                                                                        | 17          |
| 3. Items to be Set as Tool Data .....                                                                                                                                       | 21          |
| SECTION 4 MATERIAL DATA SETTING .....                                                                                                                                       | 32          |
| 1. What is the Function of Material Data Setting? .....                                                                                                                     | 32          |
| 2. Material Data Setting Procedure .....                                                                                                                                    | 34          |
| 3. Items to be Set as Material Data .....                                                                                                                                   | 37          |
| SECTION 5 ONE-TOUCH IGF PARAMETER SETTING .....                                                                                                                             | 46          |
| 1. What is the Function of an IGF Parameter? .....                                                                                                                          | 46          |
| 2. Parameter Setting Procedure .....                                                                                                                                        | 48          |
| 3. One-touch IGF Parameters .....                                                                                                                                           | 50          |
| SECTION 6 FINISHED SHAPE DEFINITION<br>(SHAPE DEFINITION) .....                                                                                                             | 80          |
| 1. What is the Function of "Finished Shape Definition"? .....                                                                                                               | 80          |
| 2. Basic Blank Shape Definition<br>(Designation of Blank Material, Basic Blank Material Shape<br>(Outline of Blank Material Shape), and Type of Blank Material Shape) ..... | 81          |
| 3. TURNING MACH SHAPE Definition .....                                                                                                                                      | 85          |
| 4. Finished Shape Definition for Multiple Machining (Optional) .....                                                                                                        | 126         |
| 5. SIDE GENERATING SHAPE Definition .....                                                                                                                                   | 154         |
| 6. FACE GENERATING/BACK GENERATING SHAPE Definition (Optional) .....                                                                                                        | 168         |

|                                                                                                                                   | <u>PAGE</u> |
|-----------------------------------------------------------------------------------------------------------------------------------|-------------|
| SECTION 7 BLANK MATERIAL SHAPE DEFINITION<br>(SHAPE DEFINITION) .....                                                             | 184         |
| 1. What is the Function of “Blank Material Shape Definition”? .....                                                               | 184         |
| 2. AVE. BLANK SHAPE Definition .....                                                                                              | 185         |
| 3. BLANK SHAPE Definition .....                                                                                                   | 190         |
| SECTION 8 SETUP INPUT .....                                                                                                       | 201         |
| 1. What is the Function of “Setup Input”? .....                                                                                   | 201         |
| 2. Designating Bar Material Preparation<br>(Bar Feeder (Puller) Specification) .....                                              | 203         |
| 3. Division Point Setting Procedure .....                                                                                         | 203         |
| 4. CHUCK CENTER Definition .....                                                                                                  | 205         |
| SECTION 9 AUTOMATIC PROCESS DETERMINATION .....                                                                                   | 208         |
| 1. What is the Function of “Automatic Process Determination”? .....                                                               | 208         |
| 2. Determination of Machining Area .....                                                                                          | 211         |
| 3. Determination of Machining Method .....                                                                                        | 213         |
| 4. Role of the Condition Setting Function .....                                                                                   | 217         |
| 4-1. Functions .....                                                                                                              | 217         |
| 5. Data Setting Item .....                                                                                                        | 219         |
| 6. Automatic Process Determination Using the Condition Setting Function .....                                                     | 239         |
| SECTION 10 PROCESS TEST .....                                                                                                     | 240         |
| 1. What is the Function of “Process Test”? .....                                                                                  | 240         |
| 2. Test .....                                                                                                                     | 241         |
| SECTION 11 PROCESS EDIT .....                                                                                                     | 251         |
| 1. What is the Function of “Process Edit”? .....                                                                                  | 251         |
| 2. Checking the Contents of Process (Process Check Screen) .....                                                                  | 254         |
| 3. Editing the Process in Unit .....                                                                                              | 258         |
| 4. Editing the Machining Method (Turning, Special Machining) .....                                                                | 270         |
| 5. Editing the Machining Method<br>(Optional: Multi-machining Specification,<br>Contour Generating Machining Specification) ..... | 281         |
| 6. Process List Display .....                                                                                                     | 288         |

|                                                                                                        | <u>PAGE</u> |
|--------------------------------------------------------------------------------------------------------|-------------|
| 7. Editing the Finished Shape (Rough Turning, Copying, Finish Turning) . . . . .                       | 293         |
| 7-1. Selection of Process to be Edited . . . . .                                                       | 293         |
| 7-2. Motion from Cycle Reference Point to Infeed Point . . . . .                                       | 304         |
| 7-3. Motion at the End Point . . . . .                                                                 | 305         |
| 7-4. Starting and End Points for Rounding (R-CHF) and Chamfering . . . . .                             | 306         |
| 7-5. Deleting the Edited Data . . . . .                                                                | 308         |
| 7-6. Switching to the MACH. METHOD AMEND Screen . . . . .                                              | 308         |
| 7-7. Terminating the Machining Shape Editing . . . . .                                                 | 308         |
| 7-8. Shape Referencing . . . . .                                                                       | 308         |
| 8. Editing the Finished Shape (Special Turning) . . . . .                                              | 309         |
| 8-1. Selection of Process to be Edited . . . . .                                                       | 309         |
| 8-2. Deleting the Edited Data . . . . .                                                                | 317         |
| 8-3. Switching to the MACH. METHOD AMEND Screen . . . . .                                              | 317         |
| 8-4. Terminating the Machining Shape Editing . . . . .                                                 | 317         |
| 9. Editing the Finished Shape (Multi-machining)<br>(Optional: Multi-machining Specification) . . . . . | 318         |
| 9-1. Selection of Process to be Edited . . . . .                                                       | 318         |
| 10. Editing the Finished Shape (Side Contour Generating Machining) . . . . .                           | 322         |
| 10-1. Selection of Process to be Edited . . . . .                                                      | 322         |
| 11. Editing the Finished Shape (Face Contour Generating Machining) . . . . .                           | 328         |
| 11-1. Selection of Process to be Edited . . . . .                                                      | 328         |
| 12. Tool Path Control . . . . .                                                                        | 338         |
| 12-1. Approach and Retract of Cutting Tool . . . . .                                                   | 338         |
| 12-2. Tool Path Control . . . . .                                                                      | 339         |
| 13. Process Test . . . . .                                                                             | 340         |
| 14. Editing the NC Program . . . . .                                                                   | 341         |
| 15. Editing the Gauging Process<br>(Optional: In-process Gauging Specification) . . . . .              | 342         |
| 16. Machining Kind (Process Kind) List . . . . .                                                       | 343         |

|                                                                                                                            | <u>PAGE</u> |
|----------------------------------------------------------------------------------------------------------------------------|-------------|
| SECTION 12 PART PROGRAM CREATION .....                                                                                     | 346         |
| 1. What is the Function of “Part Program Creation”? .....                                                                  | 346         |
| 2. Program Creating Procedure .....                                                                                        | 347         |
| 3. Sequence Numbers and Sequence Names .....                                                                               | 349         |
| 4. Output of Modal M Codes .....                                                                                           | 350         |
| 5. Automatic Generation of Optional Stop (M01) .....                                                                       | 351         |
| 6. Spindle Control .....                                                                                                   | 351         |
| 7. Coolant On/Off Control .....                                                                                            | 352         |
| 8. Tool Change Control .....                                                                                               | 352         |
| SECTION 13 TERMINATION OF ONE-TOUCH IGF OPERATION .....                                                                    | 358         |
| SECTION 14 DATA INPUT USING MATH OPERATION .....                                                                           | 359         |
| 1. Arithmetic and Function Operation Symbol .....                                                                          | 359         |
| 2. Input Examples .....                                                                                                    | 361         |
| SECTION 15 DATA INPUT USING ADDITION FUNCTION .....                                                                        | 362         |
| SECTION 16 ONE-TOUCH IGF TEMPORARY QUIT AND RECOVERY FUNCTION .....                                                        | 363         |
| SECTION 17 ANIMATION DATA .....                                                                                            | 365         |
| 1. What is the Function of “Animation Data”? .....                                                                         | 365         |
| 1-1. Tool Shape Definition .....                                                                                           | 365         |
| 1-2. Chuck Barrier Definition .....                                                                                        | 367         |
| 1-3. Tailstock Barrier Definition .....                                                                                    | 367         |
| 2. Drawing Blank Shape .....                                                                                               | 368         |
| 2-1. Definition Format .....                                                                                               | 368         |
| 2-2. User Graphic Commands (UGC) .....                                                                                     | 369         |
| SECTION 18 ONE-TOUCH IGF FOR PRECISION LATHES (OPTIONAL) .....                                                             | 378         |
| 1. Unit System .....                                                                                                       | 378         |
| 2. Upper and Lower Limits of Data Setting for Process Edit,<br>Tool Data Set and Parameter Set (Dimension parameter) ..... | 379         |
| 3. Material Data .....                                                                                                     | 380         |

|                                                                                           | <u>PAGE</u> |
|-------------------------------------------------------------------------------------------|-------------|
| SECTION 19 BAR FEEDER AND BAR PULLER FUNCTION (OPTIONAL) .....                            | 381         |
| 1. Bar Material Preparation Parameters .....                                              | 381         |
| 2. Designating Bar Material Preparation Parameter .....                                   | 384         |
| SECTION 20 ONE-TOUCH IGF ON IN-PROCESS GAUGING FUNCTION SPECIFICATION<br>(OPTIONAL) ..... | 392         |
| 1. Parameters Used for Gauging Cycles .....                                               | 392         |
| 2. Making Gauging Processes .....                                                         | 393         |
| 2-1. Gauging Cycles for Rough, Turning, Finish Turning, and Copy Processes ..             | 393         |
| 2-2. Gauging Cycle for Grooving Process .....                                             | 399         |
| 3. Process Edit Operation Precautions .....                                               | 402         |
| 4. Gauging Process Test .....                                                             | 402         |
| 5. NC Gauging Process Program .....                                                       | 403         |
| SECTION 21 ONE-TOUCH IGF WITH LOAD MONITOR SPECIFICATION (OPTIONAL) .....                 | 405         |
| 1. Setting Monitor Axis .....                                                             | 405         |
| SECTION 22 ATC SPECIFICATION (OPTIONAL) .....                                             | 408         |
| 1. ATC for LR15M-ATC .....                                                                | 409         |
| 2. ATC for LR15M-ATC/Y .....                                                              | 410         |
| 3. ATC for LR25M-ATC/Y, LR 45M-ATC/Y .....                                                | 412         |
| 4. ATC for LB15 II M-ATC/Y .....                                                          | 414         |
| SECTION 23 CONVERSION FUNCTION (OPTIONAL) .....                                           | 416         |
| 1. Operating Procedure .....                                                              | 416         |
| 2. Items to be Converted .....                                                            | 419         |
| SECTION 24 SUB-SPINDLE AND FACING 2 SPINDLES .....                                        | 424         |
| 1. Shape Definition .....                                                                 | 424         |
| 2. Setup Input .....                                                                      | 426         |
| 3. Automatic Process Determination and Condition Setting .....                            | 431         |
| 4. Machining Test .....                                                                   | 435         |
| 5. Process Edit .....                                                                     | 438         |
| 6. Machining Program Creation .....                                                       | 453         |

|                                                                                                                  | <u>PAGE</u> |
|------------------------------------------------------------------------------------------------------------------|-------------|
| 7. Tool Data Setting .....                                                                                       | 456         |
| 8. Parameter Setting .....                                                                                       | 458         |
| SECTION 25 Y-AXIS MACHINING (OPTIONAL) .....                                                                     | 461         |
| 1. Shape Definition .....                                                                                        | 461         |
| 1-1. Shape Definition for Multi-machining<br>(Optional: Multi-machining Including Y-axis Machining) .....        | 461         |
| 1-2. SIDE GENERATING Y SHAPE Definition .....                                                                    | 473         |
| 2. Automatic Process Determination .....                                                                         | 476         |
| 2-1. Machining Kinds to be Automatically Determined .....                                                        | 476         |
| 3. Process Edit .....                                                                                            | 477         |
| 3-1. Check of Process Content (Process Check Screens) .....                                                      | 477         |
| 3-2. Editing Machining Method (Multi-machining Y)<br>(Optional: Multi-machining, Y-axis Specifications) .....    | 480         |
| 3-3. Editing the Finished Shape for Multi-machining Y<br>(Optional: Multi-machining, Y-axis Specification) ..... | 483         |
| 3-4. Editing the Finished Shape<br>(Side Contour Generating Y Machining) .....                                   | 486         |
| 3-5. Machining Kind List .....                                                                                   | 488         |
| 4. NC Program Output .....                                                                                       | 489         |
| 4-1. Preparation and Modal Check in Multi-machining Y Process .....                                              | 489         |
| 4-2. Tool Path in Multi-machining Y .....                                                                        | 491         |
| 4-3. NC Program Output for Hole Machining .....                                                                  | 492         |
| 4-4. NC Program Output for Side Contour Generating Y .....                                                       | 495         |
| 4-5. NC Program Output for Side Keyway Y .....                                                                   | 496         |
| 4-6. Blank UGC (User Graphic Commands) .....                                                                     | 499         |
| 5. Process Test .....                                                                                            | 500         |
| 5-1. Process Test (Optional: Multi-machining, Y-axis Specifications) .....                                       | 500         |
| 6. Parameter Setting .....                                                                                       | 503         |
| PART II ERROR LIST .....                                                                                         | 504         |