

**FT600 TURNING CENTERS
MILL TURN WITH Y-AXIS FUNCTION
(WITH FANUC SYSTEM FT6)
OPERATION MANUAL**



C O N T E N T S

Introduction

Chapter 1 Outline of Machine

Chapter 2 Specifications of Machine

Chapter 3 Design and Structure

Chapter 4 Transportation and Installation

Chapter 5 Lubrication and Oil Filling

Chapter 6 Hydraulic Pump Unit

Chapter 7 Operation

Chapter 8 Adjustment

Chapter 1 Outline of Machine

Page

1. General Structure of Machine	1-01
---------------------------------------	------

Chapter 2 Specifications of Machine

	Page
1. Specifications of Basic Machine	2-01
2. Standard Accessories	2-03
3. Optional Accessories	2-04
4. Specifications of Numerical Control Unit	2-05
4-1 Basic Functions	2-05
4-2 Optional Functions	2-08

Chapter 3 Design and Structure

	Page
1. Headstock	3-01
2. C-Axis Gear Box	3-01
3. Turning Turret (Turret A)	3-01
4. Turret with Tool Spindles (Turret B)	3-02
5. Turret Unit	3-02
6. Carriage	3-03
7. Bed	3-03
8. Cover and Splash Guard	3-03
9. Operating Station	3-04
10. Hydraulic Pump Unit	3-04
11. Hydraulic Chuck	3-04
12. Coolant System	3-04
13. Work Light	3-05
14. Chip Disposal Equipment (Chip Conveyor)	3-05
15. Control Enclosure	3-05
16. Wiring Duct	3-06
17. Y-Axis Function	3-06

Chapter 4 Transportation and Installation

	Page
1. Transportation	4-01
1-1 Cautions before Lifting and Transporting the Machine	4-01
1-2 Cautions When Lifting and Transporting the Machine	4-02
2. Foundation and Installation	4-05
2-1 Foundation	4-05
2-2 Installation	4-05
3. Assembly and Cleaning	4-06

Chapter 5 Lubrication and Oil Filling

	Page
1. Headstock and C-Axis Gear Box	5-01
2. Supporting Bearings for Ball Screws for X, Z and Y Axes	5-01
3. Slideways for X, Z and Y Axes and Ball Screws for X, Z and Y Axes	5-02
4. Turret Unit	5-02
5. Tool Spindles	5-04
6. Coolant System	5-05
Lubrication Diagram	5-06
Table of Recommended Oils and Greases	5-07

Chapter 6 Hydraulic Pump Unit

	Page
1. Hydraulic Circuits	6-01
1) Source Pressure	6-01
2) Turret Unit Indexing Circuit	6-01
3) Turret Unit Clamping Circuit	6-02
4) Turret Indexing Circuit	6-02
5) Turret Clamping and Unclamping Circuit	6-03
6) Face Milling/Side Milling Change-over Circuit for Tool Spindle Drive Unit	6-03
7) Hydraulic Balancing Circuit for Turret with Tool Spindles (Y-Axis Counterbalancer)	6-03
8) Circuit for ID/OD Chucking by Hydraulic Chuck	6-04
9) Circuit for C-Axis Brake Operation and Main Spindle Clamping	6-04
2. Changing of Hydraulic Oil and Cleaning	6-05
3. Hydraulic Circuit Diagram	6-07

Chapter 7 Operation

	Page
1. Preparation for Operation	7-01
1-1 Checking before Operation	7-01
1-2 Turning Power Switches ON	7-02
2. Checking of Operation	7-03
2-1 Feed	7-03
2-2 Return to Reference Point for X, Z and Y Axes	7-07
2-3 Setting of Origin of C axis	7-08
2-4 Turret Indexing	7-09
2-5 Turret Unit Indexing	7-10
2-6 Coolant	7-11
2-7 Main Spindle	7-11
2-8 Tool Spindles	7-14
2-9 Machine Lock	7-15
2-10 Dry Run	7-16
2-11 Optional Block Skip	7-17
2-12 Optional Stop	7-17
2-13 Main Spindle Clamp	7-17
2-14 Manual Absolute	7-18
2-15 Chip Conveyor	7-19
3. Automatic Operation	7-19
3-1 Preparation for Automatic Operation	7-19
3-2 Correction by First Workpiece	7-20

	Page
4. Stopping of Machine	7-24
4-1 Stopping of Machine During Operation	7-24
4-2 Stopping of Machine at End of Work	7-25
5. Running-in before Operation	7-25
6. Door Interlock	7-26
7. Interlocks for Operation	7-27
8. NC Panel	7-30
9. Operating Station on Machine	7-31

Chapter 8 Adjustment

	Page
1. Preload of Main Spindle Bearings	8-01
2. Adjustment of Taper Gibs	8-01
3. Replacement of Brush for Electromagnetic Clutch	8-05
4. Adjustment of V-Belts between Main Spindle and Transmission	8-05
5. Adjustment of V-Belts for Tool Spindle Drive Motor	8-07
6. Adjustment of Limit Switches	8-08
7. Layout of Electric Equipment for Basic Machine	8-12