

A large, stylized white graphic on an orange background, resembling a stylized 'M' or a series of overlapping curved lines.

Mazak

PROGRAMMING MANUAL


MAZATROL SMART

(For Turning Machines)

MAZATROL Program

MANUAL No.: H745PA0014E

**PROGRAMMING
MANUAL**



PROGRAMMING MANUAL

MAZATROL SMART

(For Turning Machines)

MAZATROL Program

MANUAL No.: H745PA0014E

Before using this machine and equipment, fully understand the contents of this manual to ensure proper operation. Should any questions arise, please ask the nearest Technical Center or Technology Center.

IMPORTANT NOTICE

1. Be sure to observe the safety precautions described in this manual and the contents of the safety plates on the machine and equipment. Failure may cause serious personal injury or material damage. Please replace any missing safety plates as soon as possible.
2. No modifications are to be performed that will affect operation safety. If such modifications are required, please contact the nearest Technical Center or Technology Center.
3. For the purpose of explaining the operation of the machine and equipment, some illustrations may not include safety features such as covers, doors, etc. Before operation, make sure all such items are in place.
4. This manual was considered complete and accurate at the time of publication, however, due to our desire to constantly improve the quality and specification of all our products, it is subject to change or modification. If you have any questions, please contact the nearest Technical Center or Technology Center.
5. Always keep this manual near the machinery for immediate use.
6. If a new manual is required, please order from the nearest Technical Center or Technology Center with the manual No. or the machine name, serial No. and manual name.

Issued by *Manual Publication Section, Yamazaki Mazak Corporation, Japan*

CONTENTS

Page

1	MAZATROL PROGRAM CONFIGURATION.....	1-1
1-1	Program Configuration	1-1
2	PROGRAM COORDINATE SYSTEM	2-1
3	PROGRAM CREATION.....	3-1
3-1	Procedure for Program Creation	3-1
3-2	Common Unit	3-6
3-2-1	Setting unit data (common data)	3-6
3-3	Materials Shape Unit (MATERIAL)	3-8
3-3-1	Setting unit data	3-8
3-3-2	Setting sequence data.....	3-8
3-4	Turning Units	3-11
3-4-1	Types of turning units	3-11
3-4-2	Procedure for selecting turning unit.....	3-11
3-5	Bar-Materials Machining Unit (BAR)	3-12
3-5-1	Setting unit data	3-12
3-5-2	Setting tool sequence data	3-15
3-5-3	Setting shape sequence data	3-20
3-6	Copy-Machining Unit (CPY)	3-25
3-6-1	Setting unit data	3-25
3-6-2	Setting tool sequence data	3-27
3-6-3	Setting shape sequence data	3-28
3-7	Corner-Machining Unit (CORNER).....	3-29

3-7-1	Setting unit data	3-29
3-7-2	Setting tool sequence data	3-30
3-7-3	Setting shape sequence data	3-32
3-8	Facing Unit (FACING)	3-33
3-8-1	Setting unit data	3-33
3-8-2	Setting tool sequence data	3-33
3-8-3	Setting shape sequence data	3-35
3-9	Threading Unit (THREAD)	3-36
3-9-1	Setting unit data	3-36
3-9-2	Setting tool sequence data	3-39
3-9-3	Setting sequence data	3-41
3-10	Grooving Unit (T. GROOVE)	3-44
3-10-1	Setting unit data	3-44
3-10-2	Setting tool sequence data	3-47
3-10-3	Setting shape sequence data	3-50
3-11	Turning Drilling Unit (T. DRILL)	3-54
3-11-1	Setting unit data	3-54
3-11-2	Setting tool sequence data	3-55
3-11-3	Setting shape sequence data	3-60
3-12	Turning Tapping Unit (T. TAP)	3-61
3-12-1	Setting unit data	3-61
3-12-2	Setting tool sequence data	3-63
3-12-3	Setting shape sequence data	3-64
3-13	Milling Unit	3-64
3-13-1	Machining method	3-65

3-14	Point Machining Units.....	3-65
3-14-1	Types of point machining units.....	3-66
3-14-2	Procedure for selecting point machining unit	3-66
3-14-3	Unit data and automatic tool development of the point machining unit	3-67
3-14-4	Automatic tool development for carbide drills.....	3-77
3-14-5	Tool sequence data of the point machining unit.....	3-78
3-14-6	Tool path of the point machining unit	3-82
3-14-7	Shape sequence data of the point machining unit	3-112
3-15	Line Machining Units	3-116
3-15-1	Types of line machining units	3-116
3-15-2	Procedure for selecting line machining unit.....	3-117
3-15-3	Unit data, automatic tool development and tool path of the line machining unit....	3-118
3-15-4	Tool sequence data of the line machining unit.....	3-158
3-15-5	Precautions in line machining.....	3-161
3-15-6	Automatic corner override	3-165
3-15-7	Shape sequence data of the line machining unit.....	3-167
3-16	Other Units	3-181
3-17	Manual Program Machining Unit (MANL PRG)	3-182
3-17-1	Setting unit data	3-182
3-17-2	Setting sequence data.....	3-183
3-18	M-Code Unit (M-CODE)	3-185
3-18-1	Setting unit data (M-code)	3-185
3-19	Subprogram Unit (SUB PRO).....	3-186
3-19-1	Setting unit data	3-186
3-19-2	Setting sequence data.....	3-187

3-20	End Unit (END).....	3-188
3-20-1	Setting unit data	3-188
3-20-2	Setting sequence data.....	3-191
3-21	Coordinate Measuring Unit (MMS)	3-192
3-21-1	Procedure for selecting the MMS unit	3-192
3-21-2	Setting unit data	3-192
3-21-3	Setting sequence data.....	3-193
3-21-4	Type of measurement	3-194
3-22	Workpiece Measuring Unit (WORK MES)	3-198
3-22-1	Procedure for selecting workpiece measuring unit.....	3-198
3-22-2	Setting the unit data	3-198
3-22-3	Setting the sequence data.....	3-199
3-22-4	Selection of a measurement type.....	3-200
3-22-5	Offset value and the direction of offset.....	3-208
3-22-6	Offset judgment	3-211
3-23	Tool Measuring Unit (TOOL MES).....	3-212
3-23-1	Procedure for selecting tool measuring unit	3-212
3-23-2	Setting the unit data	3-212
3-23-3	Setting the sequence data.....	3-213
3-23-4	Measuring patterns.....	3-214
4	TPC DATA SETTING	4-1
4-1	Operating Procedure for Setting TPC (Tool-Path Control) Data.....	4-1
4-2	Description of Each TPC Data Item.....	4-4
5	PROGRAM EDITING.....	5-1

5-1	Operating Procedures for Editing Programs.....	5-1
5-2	Search	5-2
5-3	Insertion.....	5-5
5-4	Deletion	5-9
5-5	Copy	5-13
6	PROGRAM CREATING/EDITING FUNCTIONS	6-1
6-1	Help Function	6-1
6-2	Automatic Crossing-Point Calculation Function.....	6-2
6-2-1	Automatic crossing-point calculation function in the turning unit.....	6-2
6-2-2	Automatic crossing-point calculation in the line machining units.....	6-10
6-3	Automatic Cutting-Conditions Setting Function	6-14
6-4	Tool Data Window	6-16
7	SAMPLE PROGRAMS	7-1
8	THREE-DIGIT G-FORMAT.....	8-1
8-1	Outline	8-1
8-2	Detailed Description	8-1
8-3	Three-Digit G-Format of MAZATROL Program	8-2
8-4	Various Data Description Using G10	8-19