




Q12

1200 PSI Hard Surface Cleaner



Before Use


1




2




OR Auto-Fill and Auto-Dump (Continuous Run)



3




4




5



6



7



8



9



10

