



Diamond Steel Co, Inc.
971 N. George Washington Blvd.
Yuba City, CA 95993
www.diamondbilt.com
Phone: 530-674-8577
Fax: 530-674-7339
Email: sales@diamondbilt.com



DIAMOND BILT PM60 & PM100 EMULSION SPRAYER

With a Diamond Bilt PM060 or PM100, efficiency and ease of use are a top priority. These units are a perfect companion for contractors working small job, such as filling potholes or minor trench work. Each unit comes standard with a 25' spray wand hose as well as Diamond Bilt's light weight Spray Wand, featuring a stay cool handle and no drip tip. Our skid units are designed to fit in the back of a pick-up truck with built in fork lift pockets for easy mobility.

Options and customization available to make sure your unit fits all of your needs.

CALL TODAY! 530-674-8577

Diamond Steel Co, Inc. is a family owned and operated company that strives to provide well-engineered, high-quality construction equipment.

FEATURES


- Available as a Skid or Trailer Unit
- 60 or 100 Gallon Rectangular Tank
- Electric Start Engine
- Electric Start LPG Burner with Regulator and Gauge
- Flush/Recovery Tank for quick clean up of the pump, plumbing, hoses, and Spray Wand
- Plumbing and Spray Wand Recirculation keeps tack evenly heated and prevents emulsion from solidifying in the plumbing hose or Spray Wand
- 5' light weight Diamond Bilt Spray Wand featuring stay cool handle and no drip tip
- 25-foot Spray Wand hose
- D-Wraps for Easy Hose Storage
- Standard Color: Black



Standard PM060



PM060



PM100

POPULAR OPTIONS

- 50-ft or 100-ft Spray Wand hose
- 115-Volt Out-of-Service Tank Heater with Thermostat
- Spring Rewind Hose Reel with Hose Guides
- LPG Hand Torch (176,000 BTU)
- Additional Colors Available
- Call for Additional Customizations

Advantages of Choosing a Diamond Bilt Pave-Mate

- Quality and longevity of the units is our priority.
- Most standard parts kept in stock ready to ship.
- 1 year unlimited warranty.
- Customization and special options available.
- Knowledgeable staff to help troubleshoot any issues.