

# ***PARTS LIST***

**VERTICAL MACHINING CENTER**

**MCV-610AP**

**LEADWELL<sup>®</sup>**

**LEADWELL CNC MACHINES MFG., CORP.**



*C O N T E N T S*

---

1. OUTLINE DRAWING.....	P. 1
2. FOUNDATION DRAWING.....	P. 2
3. LIFTING-FORK LIFTER.....	P. 3
4. LIFTING-OVERHEAD CRANE.....	P. 4
5. SPINDLE ASSEMBLY DRAWING.....	P. 5
6. SPINDLE HEAD ASSEMBLY DRAWING.....	P. 8
7. TWO STAGES CYLINDER ASSEMBLY DRAWING.....	P. 11
8. THE LUBRICATION ASSEMBLY DRAWING OF SPINDLE HEAD.....	P. 14
9. COLUMN ASSEMBLY DRAWING.....	P. 16
10. BASE ASSEMBLY DRAWING.....	P. 21
11. SADDLE AND TABLE ASSEMBLY DRAWING.....	P. 24
12. THE LUBRICATION ASSEMBLY DRAWING OF SADDLE.....	P. 28
13. TABLE DIMENSION DRAWING (STANDARD).....	P. 30
14. TABLE PLATE WITH 3R SYSTEM DRAWING.....	P. 31
15. THE LUBRICATION ASSEMBLY DRAWING OF TABLE.....	P. 32
16. THE LOOP DRAWING OF PNEUMATIC SYSTEM.....	P. 34
17. THE ROUTE DRAWING OF PNEUMATIC.....	P. 35
18. CHIP-PROOF SHEET METAL ASSEMBLY DRAWING.....	P. 36
19. AUTOMATIC TOOLING CHANGER ASSEMBLY DRAWING.....	P. 42
20. TRANSMISSION SYSTEM ASSEMBLY DRAWING OF X AND Y AXIS.....	P. 48
21. TRANSMISSION SYSTEM ASSEMBLY DRAWING OF Z AXIS.....	P. 51
22. ELECTRIC CONTROLLING CABINET ASSEMBLY DRAWING.....	P. 54