





ASSY NOTE
THE INDICATED INITIAL
SETTINGS SHOULD BE OBTAINED
THE LID THE REPAIR AT 0.63 CLEARANCE
DUE TO INITIAL WARPAGE
OF THE LID ETC. THE FINAL
ADJUST IS GIVEN DIMENSIONS
WHY VARY



TURN C LOWERS LID
TIP APPROX. 0.05"

6' MILET - EZ-113-3
RETURN - YY-85A-7
LID SEAL - YY-81
ASSY - E-334, E-335, SK-122
PARTS LIST - SKT-17
FILE NO. 66

NO. 1	DATE	BY	REVISION
1	15 APR 77	J.F.F.	1
LAWRENCE & SONS CO. 6' HORNE FORMER 42" DIA CYL MOUNT OVERHEAD MOUNTING NO. 107A-005211 DATE 15 APR 77 BY J.F.F. CHECKED J.F.F. REVISIONS 1.019 1.020 1.021 1.022 1.023 1.024 1.025 1.026 1.027 1.028 1.029 1.030 1.031 1.032 1.033 1.034 1.035 1.036 1.037 1.038 1.039 1.040 1.041 1.042 1.043 1.044 1.045 1.046 1.047 1.048 1.049 1.050 1.051 1.052 1.053 1.054 1.055 1.056 1.057 1.058 1.059 1.060 1.061 1.062 1.063 1.064 1.065 1.066 1.067 1.068 1.069 1.070 1.071 1.072 1.073 1.074 1.075 1.076 1.077 1.078 1.079 1.080 1.081 1.082 1.083 1.084 1.085 1.086 1.087 1.088 1.089 1.090 1.091 1.092 1.093 1.094 1.095 1.096 1.097 1.098 1.099 1.100			