

Holland Reefer Service B.V.
Theemsweg 48 - 3197 KM - Rotterdam Bollek
TEL. +31 (0) 181 234 244 FAX. +31 (0) 181 234 249



* VPhen choice, please mark if true.

GENSET INSPECTION REPORT

	number: 2 S 6 7 0 0 0 5 3 L	Manufacturer: Thermoli	n	Location:	Date: 2.1	6-22
Visua	al check					
Ck F	ail	in the second	Ok Fa	ail		
<u></u>	Genset is free from damage and corrosion		V	Battery condition		
~	Decals are present, undamaged and clearly legible			Engine oil and pressure		
	Machine covers correctly fitted and in good condition			Coolant level		
V	Motor and Alternator mounting condition			Belt condition and proper tension		
1	No unusual noises, viberations etc.			Clean air cleaner		
V	Inspect for unit or fluid leaks			Power receptacle condition		
U	Unit and radiator coil are clean	1.18	V	Switches and lights		
V	Controlbox condition		V	Data and certification plates		
. VI	Electrical supply voltage 455	v 462	<u> </u>	458 V	61	H:
Opera	ational check	***				
Ok F	all	W		Ŕ	_	
V	Oil pressure		Ų	PSI	UNEC CONTROL OF THE C	
V	Hour meter reading 2		6606	Hour		
V	Indicator lights	300			Al	A* **
ldenti	fication	Servic	e enginee	me (76-8	
	W.			1500	Tr.	
Туре	Clip Unders	Lunge Comm	ents:			117 h
17.72	number 08736 F 947		JIIIV.	197	100	
Mode						
Ccolin		5				L. a. web.
	Manufacturus Vomb of		1.0			