3.2 Checking Shipment

Every item on the shipping list should be checked against the contents of the shipment. Compare the certified assembly and installation drawings with the final shipment. (Check for screen surface, feed nozzle and nozzle operator, etc.)

3.3 Handling the Assembled Screen

Use lifting holes on top of screen box (one on each side) for lifting and carrying. Approximate weights of the three screen configurations are:

- 2' Wide Single 660 lbs.
- 4' Wide Double 1280 lbs.
- 6' Wide Triple 1820 lbs.

3.4 Storage

If the screen is to be stored before installing, leave it in the shipping crate. The screen surface should be carefully protected from possible damage. Keep the electrical components dry.