

, (

....

q.			V a l. v e s								Motors				
A Cost		1	2	٤	4	5	G		8	Pulper Mi	CMS M2	Prangs M3	Conveyor M4	Sorter M5	
1	Slushing water + Furnish	open	shut	open	slut	shut:	shut	shut	shut	On	off	off	OH	off	
2	Stualing	shut	shut	shut	shut	shut.	shut	slint	shut	on	of.f	off	off	off	
.3	Preditution	នាពេប	open	open	shut	shut	shut	shut	shut	on	off	off	off	off	
4	Postdilution F discharge	shut	oben	shut	open	open	open	shut	shut	on	on	on	off	off	
5	Flushing water inlet	shut	oben	open	shut	OLven	shut.	sluit	មាល៤	off	on	of f	off	off	
6	Flushing	shut	shut.	shut.	shuL	Oben	open	shut.	មារាជ	off	on	On	off	off	
γ	Rejects discharging	shut	open	shut	open	shut.	shut.	open	shut	υff	on	off	off	On	
	Flushing out heavy contamination	នhut	sluit	ទាំពេ	shut	shut	shut	open	oben	off	off	ofE	off	off	