



RODS  
THREADED  
BOTH ENDS

HYD.  
JACK

SEE PLATE  
DWG. ON PAGE 12

RECOMMENDED REMOVAL OF  
BOTTOM BEARING & HOUSING