

Scope of rebuild:

The following is description of the work that was done on this refiner:

1. Disassembled refiner
2. Installed new sleeve, bearings and seals
3. Installed new packing
4. Installed new Helicoils for plates
5. Machined the door surface on base and door
6. Replaced Gauge Panel
7. Replaced the thrust washers and bushings on the door hinges
8. Rebuilt adjusting mechanism with new worm shaft bearings and seals. New sliding head seals. New clutch parts and handwheel.
9. Rebuilt gearmotor.
10. Reassembled and trammed.
11. Supplied new bolts.
12. Primed and painted

