



LAMCOR CORPORATION
10 Chenell Drive
Concord NH 03301
Phone - (603) 647-6386
Fax - (603) 647-6388
E-Mail - "info@lamcor.com"

Mechanical Rebuild Report

Customer Information

Customer: Canam

Location: n-a

Customer Contact: Jake Daniels

Address: 44 Old Princeton Rd

Fitchburg, MA 01420

Telephone: (978) 343-4400

Distribution

Send Report to:

Copies to: Customer

Equipment Information

Beloit 30" Double-Disk Refiner

Beloit Shop Number D-2749

Lamcor Shop Number M-1579

Lamcor

Report Prepared by: AMK

Issue Date: August 10, 2018

Scope of rebuild:

The following is description of the work that was done on this refiner:

1. Disassembled refiner
2. Installed new rotating assembly with shaft, bearings and seals (Can-Am supplied item)
3. Installed new packing sleeve
4. Installed rebuilt 30" splined rotating head and hub
5. Installed new packing
6. Repaired Stainless liner on #1 surface (all surfaces now lined)
7. Installed new Helicoils for plates
8. Repaired the eroded areas in the refining cavity
9. Machined the door surface
10. Replaced Gauge Panel
11. Replaced the thrust washers and bushings on the door hinges
12. Rebuilt adjusting mechanism with new worm shaft bearings and seals. New sliding head seals. New clutch parts and handwheel.
13. Rebuilt gearmotor.
14. Reassembled and trammed.
15. Supplied new bolts.
16. Primed and painted

