

**GRAPHITE MILLING MACHINE**  
**SNC43/64-A**  
**PROGRAMMING MANUAL**



SE047E-9206

# CONTENTS

## PREFACE

1.	PROGRAMMING OVERVIEW .....	1-1
2.	MACHINE CONFIGURATION .....	2-1
2.1	Machine Overview .....	2-1
2.2	Machine Origin .....	2-6
2.2.1	Coordinate system and traverse range .....	2-6
2.2.2	Machine origin .....	2-6
2.3	Interference Range by ATC Unit .....	2-8
2.4	Interference Range by Tool Length Measuring Unit .....	2-12
2.5	Interference Range by Wet-Cut Unit .....	2-14
2.6	Table Shape and Traverse Range .....	2-18
2.7	Spindle Nose Shape .....	2-20
3.	TOOLING .....	3-1
3.1	Tool Selection .....	3-1
3.1.1	Cutting tips .....	3-1
3.1.2	Tool holders .....	3-1
3.2	Limitation of Tool Weight and Size .....	3-3
3.3	Tooling Sheet .....	3-4
3.4	Tool Presetter .....	3-6
3.4.1	Tool presetter accuracy check .....	3-8
3.4.2	Tool length measurement .....	3-9
3.4.3	Tool diameter measurement .....	3-10
4.	FIXTURE .....	4-1
5.	PROGRAMMING PREPARATION .....	5-1
5.1	Drawing of Absolute Coordinate Value and Cutter Path Diagram .....	5-1
5.2	Machining Data List .....	5-1
5.2.1	Description of machining data list .....	5-1
5.2.2	Machining sequence .....	5-2
5.2.3	Cutting conditions .....	5-4

6.	PROGRAM .....	6-1
6.1	Program Entries .....	6-1
6.1.1	M 2-digit miscellaneous function (M function) .....	6-1
6.1.2	S 5-digit spindle speed function (S function) .....	6-4
6.1.3	T 2-digit tool function (T function) .....	6-4
6.2	Work Coordinate System .....	6-6
6.3	Tool Change Program .....	6-9
6.3.1	Tool number registration .....	6-9
6.3.2	Tool change .....	6-11
6.3.3	Subprogram examples for tool change .....	6-18
6.4	Tool Life Monitoring Function (option) .....	6-19
6.4.1	Overview .....	6-19
6.4.2	Display screen .....	6-20
6.4.3	Setting of tool life monitoring data .....	6-21
6.4.4	Format of tool life monitoring program .....	6-22
6.4.5	Tool life monitoring function and spare tool change function (option) ..	6-23
6.4.6	Example of tool life monitoring program .....	6-24
6.5	Subprogram .....	6-25
6.6	Tool Length Measurement (option) .....	6-26
7.	PROGRAMMING APPLICATIONS .....	7-1
7.1	Machining Drawing and Fixture .....	7-1
7.2	Tooling .....	7-1
7.3	Program Description .....	7-6
Appendix 1.	G Code .....	AP1-1
Appendix 2.	M Code List .....	AP2-1