

CNC TAPPING CENTER

TC-217/227

PROGRAMMING MANUAL

INCH

brother

BROTHER INDUSTRIES, LTD. MACHINE TOOLS DIVISION

CONTENTS

CHAPTER 1	OUTLINE OF CONVERSANTIONAL PROGRAMMING -----	1
1-1	Making a Program in Conversantional Mode -----	2
1-2	Outline of Programming -----	4
1-2-1	3 types of programs -----	4
1-2-2	Composition of a program made in conversational mode and programming flow -----	6
1-3	From Creating a Program in Conversantional Mode to Executing It -----	8
1-3-1	Step 1 (preparation for program creation) -----	10
1-3-2	Step 2 (machining data input) -----	11
1-3-3	Step 3 (workpiece machining order setting) -----	13
1-3-4	Step 4 (tool pattern setting) -----	14
1-3-5	Step 5 (setting the cutting conditions) -----	15
1-3-6	Step 6 (operation preparation) -----	16
1-3-7	Step 7 (tool mounting) -----	18
1-3-8	Step 8 (test operation) -----	20
CHAPTER 2	MACHINING DATA -----	21
2-1	What is Machining Data? -----	22
2-2	Setting the Machining Data -----	24
2-2-1	Setting procedure -----	24
2-2-2	Keys used for machining data input -----	26
2-3	Setting the Working Zero Point -----	28
2-3-1	Normal setting procedure -----	28
2-3-2	Setting by [WZRT] key -----	29
2-4	Setting the Intra-Process Return Height -----	30
2-5	Setting the Number of Workpieces -----	31
2-6	Setting the Workpiece Material -----	32
2-7	Defining the Processes -----	33
2-8	Setting the Drilling Processes -----	34
2-8-1	Center hole drilling -----	34
2-8-2	Drilling -----	44
2-8-3	Tapping -----	45
2-8-4	Reaming -----	47
2-8-5	Counterbore drilling -----	49
2-8-6	Counterbore tapping -----	49
2-8-7	Counterbore reaming -----	52

2-8-8	Tapping by rolled tap	53
2-8-9	Counterbore tapping by rolled tap	53
2-9	Setting the Milling Processes	54
2-9-1	Face milling	54
2-9-2	Facing	60
2-9-3	Pocketing	68
2-9-4	Contouring	79
2-9-5	Chamfering	94
2-10	Setting the Non-cutting Processes	111
2-10-1	Coolant	111
2-10-2	Axis feed	111
2-10-3	Signal output	111
2-10-4	Subprogram call	113
2-10-5	Program stop	113
2-10-6	Coordinate system setting	114
2-11	Motion Call	119
2-11-1	Motion call	119
2-11-2	Reediting a motion	121
2-12	Ending a Main Program	122
2-13	Setting a Subprogram	124
2-14	Ending an Edit	126
2-15	Reediting Machining Data	128
2-15-1	Search	128
2-15-2	Insertion	129
2-15-3	Deletion	130
2-15-4	Transfer of processes with [DELET] of [F4] key	131
2-15-5	Function key	132
CHAPTER 3 MOTION PROGRAM		135
3-1	Definition of Motion Program	136
3-2	Motion Program Edit	138
3-3	Motion Program Reedit	139
3-4	Cautions on Operation by Motion Program	140
3-5	Thread Cutting Motion (Option)	173
CHAPTER 4 SCHEDULE PROGRAM		
4-1	Role of Schedule Program	174

4-2	Schedule Program Edit	175
4-3	Schedule Program Redit	176
CHAPTER 5 MACHINING ORDER		177
5-1	Modifying the Machining Order	178
5-2	Details of the Machining Order	180
5-3	Machining Order and Coordinate System setting	186
5-4	Execution of a Non-Cutting Process between Cutting Process	192
5-4-1	Program (process) flow	192
5-4-2	Classification of cutting processes and non-cutting processes	192
5-4-3	Example of execution of non-cutting processes	193
CHAPTER 6 TOOL PATTERN		199
6-1	Tool Pattern Modification	200
CHAPTER 7 CUUTING CONDITIONS		203
7-1	Cutting Condition Modification	204
CHAPTER 8 OPERATION PREPARATION		207
8-1	Preoperation Procedure	208
8-2	Tool Assignment Procedure	210
8-2-1	Assignment procedure	210
8-2-2	In case the point checked by [?] key cannot be calculated	212
8-2-3	Tool assignment screen and information	213
8-2-4	Selection of required tools	215
8-2-5	Forced assignment	216
8-2-6	Changing a machining function	218
8-2-7	Tool check	219
8-3	Compensation for Cutting Position	220
8-3-1	Position of compensation	220
8-3-2	Compensation setting procedure	222
8-4	Compensation for Workpiece Height Variation	224
8-5	Auxiliary Function Setting	226
8-6	Dwell Setting	228

8-7	Reassignment	230
8-7-1	When a forced assignment or function charge is made	230
8-7-2	When a process is inserted in or deleted from the machining data	230
8-7-3	When assignment data is renewed	231

CHAPTER 9 MEMORY STATUS 233

9-1	Memory Status Display	234
9-2	Data Deletion	236
9-3	Machining Data Memory Display	240
9-3-1	Machining data memory display	240
9-3-2	Deleting machining data	242
9-3-3	Copying machining data	244
9-3-4	B-axis feature selection/deletion in machining data	245
9-4	Motion Program Memory Display	246
9-4-1	Motion program memory display	246
9-4-2	Deleting motion programs	248
9-4-3	Copying motion programs	248
9-5	Schedule Program Memory Display	250
9-5-1	Schedule program memory display	250
9-5-2	Deleting schedule programs	252
9-5-3	Copying schedule programs	252
9-6	Data Bank Memory Display	254

CHAPTER 10 EXTERNAL PROGRAM INPUT/OUTPUT 257

10-1	Outline of External Program I/O	258
10-2	Bubble Memory Display	260
10-2-1	Machining data memory display	260
10-2-2	Data bank memory display	261
10-3	Data Input from Bubble Memory to the Machine	264
10-3-1	Input of machining data from bubble memory to the machine	264
10-3-2	Input of other data from bubble memory to the machine	267
10-3-3	Check mode	269
10-4	Data Output from the Machine to the Bubble Memory	272
10-4-1	Output of machining data from the machine to the bubble memory	272
10-4-2	Output of other data from the machine to the bubble memory	275

10-5 Deleting Bubble Memory Data	278
10-5-1 Deleting machining data	279
10-5-2 Deleting other data from the bubble memory	281
10-6 Formatting the Bubble Memory	284
10-7 Compatibility of Bubble Memory Data	285
10-7-1 Compatibility with the models TC-215 and TC-225	285
10-7-2 Compatibility with the model TC-321	285
10-7-3 Compatibility with the model TC-201	285
 CHAPTER 11 IN-PROCESS EDIT	 287
11-1 Program Edit or Modification during a Machine Operation	288
11-2 Program Reference during a Machine Operation	289