

VERTICAL MACHINING CENTER PROGRAMMING MANUAL

makino

SE078E-8903

CONTENTS

INTRODUCTION

1. GENERAL DESCRIPTION OF MACHINE	1- 1
2. PROCESS OF PROGRAMMING	2- 1
3. MACHINE CONFIGURATION	3- 1
3.1 Coordinate System and Axis Travel	3- 1
3.2 Machine Origin	3- 1
3.3 Table and Load Capacity	3- 3
3.4 Spindle Head Dimension	3- 8
3.5 Tool Change Arm	3-12
3.6 Automatic Tool Changer (ATC)	3-16
4. TOOLING AND FIXTURE	4- 1
4.1 Tool Selection	4- 1
4.1.1 Cutting tips	4- 1
4.1.2 Tool holders	4- 1
4.2 Maximum Tool Weight and Size	4- 3
4.2.1 FNC74-A	4- 3
4.2.2 FNC86/106/128/178/208-A GN 106-A	4- 5
4.3 Tooling Sheet	4- 6
4.4 Tool Presetter	4- 9
4.5 Fixture	4-12
4.5.1 Factor for fixture	4-12
4.5.2 Special and general-purpose fixture	4-13
5. PREPARATION FOR PART PROGRAMMING	5- 1
5.1 Drawing of Absolute Coordinate Value	5- 1
5.2 Machning Data List	5- 1
5.2.1 Description of machining data list	5- 1
5.2.2 Machining sequence	5- 2
5.2.3 Cutting conditions	5- 3
5.3 Machine Characteristics	5- 5
5.3.1 FNC74-A	5- 5
5.3.2 FNC86/106-A	5- 5
5.3.3 FNC128/178/208-A	5- 6
5.3.4 GN-106-A	5- 6

6. PART PROGRAMS	6- 1
6.1 Program Entries	6- 1
6.1.1 Miscellaneous function (M-function)	6- 1
6.1.2 Spindle speed function (S-function)	6- 6
6.1.3 Tool functions (T-function)	6- 6
6.2 Tool Number Assignment	6- 8
6.2.1 Sequential assignment beginning with pot number 01 (origin pot)	6- 9
6.2.2 Assignment of only tool numbers for some pots and spindle tool number	6-11
6.3 Tool Calling	6-15
6.4 Tool Change	6-16
6.5 Program for Accuracy Check (Boring Bar)	6-20
6.6 Sub Program	6-22
6.6.1 Tool change sub program samples	6-23
6.6.2 Tool change sub program application sample	6-25
6.6.3 Approach motion sub program application sample	6-26
6.6.4 Multiple machining sub program sample	6-28
6.7 Tool Length Measurement (Option)	6-30
6.7.1 FANUC Series 15-MA, FANUC SYSTEM 11M-A	6-30
6.7.2 FANUC Series 0-MB	6-31
6.8 Automatic Tool Changer of 59 Tools (Option)	6-33
6.8.1 Tool number assignment	6-33
6.8.2 Tool calling	6-34
6.8.3 Tool declaration function	6-34
6.8.4 FIX tool declaration function	6-35
6.8.5 Large-diameter tool declaration function	6-36
7. EXAMPLE PROGRAMS	7- 1
7.1 Parts Drawing and Setting	7- 1
7.2 Tool Offset	7- 1
7.3 Tool List	7- 1
7.4 Program Sheet	7- 7
8. G & M CODE LISTS	8- 1
8.1 G-Code (FANUC Series 15-MA)	8- 1
8.2 G-Code (FANUC SYSTEM 11M-A)	8- 3
8.3 G-Code (FANUC Series 0-MB)	8- 6
8.4 Variable List (FANUC Series 15-MA and FANUC SYSTEM 11M-A)	8- 9

8.5	Variable List (FANUC Series 0-MB)	8-10
8.6	M-Code	8-11