

(INSTRUCTION MANUAL)

"MARK" SERIES NC POWER UNIT FOR NC EDM
MACHINING CONDITIONS SETTING INSTRUCTIONS
&
JIGS AND TOOLS, AND DIELECTRIC PROCESSING

(FOR MARK X.XI)



FINE Sodick
SODICK Co., Ltd.

Vol.2.2

MACHINING CONDITIONS SETTING INSTRUCTIONS

CONTENTS

1. BASICS FOR SETTING ELECTRICAL DISCHARGE MACHINING CONDITIONS	
1) NC EDM Spark Discharge.....	1
2) Voltage and Current Waveforms.....	5
3) Open-Circuit Voltage between Electrodes and Mean Machining Voltage.....	7
4) Pulse Energy and Mean Machining Current.....	9
2. MACHINING CONDITIONS SETTING PROCEDURE AND PARAMETERS	
1) Machining Conditions Calling and Setting Procedures.....	12
2) Individual-File Conditions Setting and Modification.....	28
3) Types of C Code Parameters.....	29
4) Pulse Setting Parameters.....	30
5) Machining Condition Adjusting Parameters.....	42
6) SIX-LORAN Motion Parameters.....	48
3. MACHINING PERFORMANCE VARIATION	
1) EDM Machining Performance Factors.....	50
2) Surface Roughness and Machining Rate Characteristics	51
3) Electrode Wear Ratio and No-wear.....	58
4) Cu-St± (Reversed Polarity) Machining Characteristic Data.....	62
5) GRAPHITE-STEEL DATA COLLECTION METHOD.....	70
6) Cuw-STEEL DATA COLLECTION METHOD.....	86
7) TEST FOR CHANGING OF 3PHASE INPUT VOLTAGE	93

JIGS AND TOOLS, AND DIELECTRIC PROCESSING

CONTENTS

1. NC EDM JIGS AND TOOLS

1) List of Instruments, Tools and Materials	
Required for NC EDM	- - - - - 1
2) Electrode Holders and Shanks	- - - - - 4
3) Workpiece Mounting Jigs and Tools	- - - - - 18

2. DIELECTRIC PROCESSING

1) Conception of Dielectric Processing	- - - - - 26
2) Injection Flushing	- - - - - 30
3) Suction Flushing	- - - - - 38
4) Side Flushing	- - - - - 41