


MAKINO

PARTS MANUAL (V0718I-P3E-XB)



S56

S 56

PARTS MANUAL

SPINDLE 12K STD
MAS403 BT40

5VS010B-01



S 56

PARTS MANUAL

COLUMN
900 MM STROKE

5VS020B-02



S 56

PARTS MANUAL

BED
W/O APC

5VS030B-02



S 56

PARTS MANUAL

SADDLE

5VS040B-01



S 56

PARTS MANUAL

TABLE
1000 X 500 MM

5VS050B-02



S 56

PARTS MANUAL

SPINDLE COOLING

5VS060A-01



S 56

PARTS MANUAL

PNEUMATIC

5VS065B-Z01



S 56

PARTS MANUAL

COOLANT TANK
STD.

5VS081B-Z03



S 56

PARTS MANUAL

SPLASH GUARD
X = 900 MM

5VS102B-01



S 56

PARTS MANUAL

ATC 20D / 30D

5VS12XB-XX

