

I-MAP

OSP7000M/700M

EDIT FUNCTION (2nd Edition)

Pub. No. 3837-E-R1 (ME51-052-R2) Aug. 1995




TABLE OF CONTENTS

PAGE

SAFETY PRECAUTIONS

SECTION 1	I-MAP EDIT FUNCTION	1
1.	Outline	1
2.	Outline of Individual Functions	2
2-1.	File Editing Function	2
2-2.	Interactive I-MAP Function	2
2-3.	Point Calculation Function	4
3.	I-MAP Edit Mode	4
4.	Selections Of Operation Modes	4
5.	Background Operation Function	5
6.	Data Setting Screen Configuration	5
7.	Controls on Operation Panel	6
7-1.	Functions of Keys	7
8.	Function Data Setting Procedure	8
8-1.	Setting Data at the Column at which Console is Located	8
8-2.	Altering Data Already Set	9
8-3.	Deleting Data Already Set and Leaving that Column Black	10
9.	Unit Systems	11
10.	Setting of Feedrate Data	12
SECTION 2	OPERATIONS OF I-MAP EDIT FUNCTION	13
1.	Selection of I-MAP Edit Function	14
2.	Selection of Program Creation or Amend Operation	15
3.	Designation of Program File Name	17
3-1.	Supplementary Explanations for Designating Program Files	18
4.	Selection of Program to be Edited	19
4-1.	Supplementary Explanations for Program Selection	20

	<u>PAGE</u>
5. File Editing Operations	21
5-1. Program Editing	24
5-2. Inserting a Line	30
5-3. Deleting a Line	31
5-4. Inserting a Character	32
5-5. Deleting a Character	33
5-6. Find	34
5-7. Change	36
5-8. Copy, Move and Insert	37
5-8-1. Copy	38
5-8-2. Move	39
5-8-3. Insert	40
5-9. Erasing a Line	41
5-10. Delete	42
5-11. Completion of Editing	43
SECTION 3 INTERACTIVE I-MAP FUNCTION	44
1. Fundamental Concept	44
2. Operation Status Transfer Diagram	45
3. Operations in Interactive I-MAP Function	46
3-1. Calling Out the Cycles	46
3-2. Operations In Fixed Cycle Function	47
3-2-1. Pattern Selection	47
3-2-2. Data Setting	49
3-2-3. Block Insert Operation	51
3-2-4. Data Setting Screens and Program Formats for Fixed Cycles	53
3-2-5. Supplementary Explanation for Fixed Cycle Programming	60
3-3. Operations in Hole Pattern Function	61
3-3-1. Pattern Selection	61
3-3-2. Data Setting	63
3-3-3. Confirmation of Input Data	65
3-3-4. Block Insert Operation	66
3-3-5. Data Setting Screens and Program Formats of Hole Position Patterns	68

	<u>PAGE</u>
3-4. Operation for Milling Cycles	73
3-4-1. Pattern Selection	73
3-4-2. Data Setting	75
3-4-3. Confirmation of Input Data	77
3-4-4. Block Insert Operation	78
3-4-5. Data Setting Screens and Program Formats of Milling Cycles	80
3-4-6. Supplements	89
3-4-7. Restrictions	93
3-4-8. Check Items [For round pocket milling, circle round milling (outside and inside), round milling corner rounding (outside and inside), and round milling corner chamfering (outside)]	94
3-4-9. Pattern Cycles	95
3-4-10. General Rules of Command Format	96
3-4-12. How to Set the Data in Incremental and Absolute Modes	99
3-4-13. Cutting Starting Point [To be set for round pocket milling, circle round milling (outside and inside), round milling corner rounding (outside and inside), and round milling corner chamfering (outside)]	100
3-4-14. Details of Pattern Cycles [For details regarding face milling, pocket milling, and round milling, refer to OSP7000M Programming Manual.]	101
3-5. Operation for True Circle Cutting Cycles	113
3-5-1. Pattern Selection	113
3-5-2. Data Setting	115
3-5-3. Block Insert Operation	117
3-5-4. Cutting Position Setting	118
3-5-5. Cycle Cancel Pattern Selection	119
3-5-6. Data Setting Screens and Program Formats of Cycle Cancel	121
3-5-7. Data Setting Screens and Program Formats of Circle Cutting Cycles	123
3-5-8. Supplementary Explanations for Circle Cutting Cycle Programming	125
3-5-9. Command Format	127
3-5-10. Operation Sequence of True Circle Cutting Cycle	128
3-5-11. Program Example	128

	<u>PAGE</u>
3-6. Reverse Conversion Operations	129
3-6-1. Selection of Reverse Conversion Function	129
3-6-2. Altering Data	131
3-6-3. Altering Block Data	132
3-6-4. Supplementary Explanations for Reverse Conversion Operations	134
SECTION 4 MENU TYPE PLAYBACK FUNCTION	135
1. Basic Concept	135
2. Operation Status Transfer Diagram	136
3. Operations in Playback Function	137
3-1. Calling Out the Functions	137
3-2. Data Setting	138
3-3. Block Insert Operation	141
3-4. Other Operations	143
3-4-1. Function key [F3] (CAL)	143
3-4-2. Cursor Movement	143
3-4-3. Automatic Generation of G Code Using FEEDRATE F Command	144
3-4-4. Automatic Generation of G56 by TOOL OFFSET NO. H Command ...	144
3-5. Supplementary Explanations for Operating Playback Function	144
SECTION 5 POINT CALCULATION FUNCTION	145
1. Fundamental Concept	145
2. Patterns of Shape Elements	146
3. Designation of Shape Elements and Data Setting Items	151
3-1. Point Designation Method	151
3-2. Line Designation Method	152
3-3. Arc Designation	154
3-3-1. Omission of One Axis Command for Arc Designation	154
3-4. Contact Circles	156
3-5. Straight Line Chamfering	156
4. Operation Status Transfer Diagram	157

	<u>PAGE</u>
5. Point Calculation Function Operations	158
5-1. Pattern Selection	159
5-1-1. Supplementary Explanations for Pattern Selection Operation	163
5-2. Selection of First Element Definition	164
5-2-1. Supplementary Explanations for Selecting First Element Definition Method	167
5-3. Data Setting for First Element	168
5-3-1. Supplementary Explanations for Setting First Element Data	170
5-4. Data Setting of Unknown Element	173
5-4-1. Supplementary Explanations for Setting Unknown Element Data	174
5-5. Selection of Second Element Definition	175
5-5-1. Supplementary Explanations for Selecting Second Element Definition Method	176
5-6. Data Setting for Second Element	176
5-6-1. Supplementary Explanations for Setting Second Element Definition Data	178
5-7. Display and Input of Calculation Result	178
5-7-1. Supplementary Explanations for Display and Input of Calculation Result	183
5-8. Last Element	185
5-9. Last Result	186
5-10. Result Data	186
5-11. Data Setting Screens	188
SECTION 6 I-MAP ERROR MESSAGES	192
SECTION 7 I-MAP ALARM MESSAGES	194