

Mazak

OPERATING MANUAL FOR

QUICK TURN 8

CONTENTS

1.	SPECIFICATIONS	1
1-1	NC Specifications	1
1-2	Standard Machine Specifications	2
2.	OPERATION PANEL	5
2-1	Main Operation Panel Layout	5
2-2	MDI and CRT Unit (Section A)	6
2-3	Switch Functions (Section B)	6
2-4	Main Operation Panel Sheet Key Layout (Section C)	9
2-5	Switch Functions (Section C)	10
2-6	Separate Operation Panel Layout (Front Cover Side)	17
2-7	Switch Functions (Front Cover Side)	18
3.	AUXILIARY FUNCTIONS	19
3-1	M Codes	19
3-2	S Codes	20
3-3	T Codes	20
4.	OPERATION	21
4-1	Startup Steps	21
4-2	Emergency Stop and Restart	21
4-3	Operating Procedure to End a Job	21
5.	USING THE INTRA-PANEL LIGHT	22
6.	PC ALARMS	23
7.	TORQUE CHARTS	27
8.	CAUTIONS FOR FANUC OT PROGRAMMING AND OPERATION	28



TOOL-EYE
QT SERIES (141, 142, 147)

NC EQUIPMENT FANUC F-OT

CONTENTS

	Page
1 OUTLINE—TOOL EYE	1
1-1 Using the Touch Sensor	1
1-2 Setting Method	2
2 PARAMETER	4
3 OPERATION	5
3-1 Setting the Tool Offset	5
3-2 Entering the Work Coordinate System Displacement	6
4 TIP MEASUREMENT	7
4-1 Outline	7
4-2 Program	7
4-3 Inputting Dimensions for Tip Measurement	9
4-4 Tip Measurement Movement ("1" is the value for Q, R, and S)	12
4-5 Tip Measurement Alarm (P/S Alarm)	15



TOOLING

QUICK TURN 8

EQUIPMENT

MAZATROL

CONTENTS

1. INTRODUCTION TO QUICK TURN 8 TOOLING	1-1
1-1 How to mount tool holders (Octagonal drum turret)	1-1
1-2 How to preset tool holder (Octagonal drum turret)	1-2-E
2. TOOLING SYSTEM	2-1
2-1 Octagonal drum turret	2-1
2-1-1 Metric system	2-1
2-1-2 Inch system	2-2-E
3. TOOL HOLDER	3-1
3-1 Octagonal drum turret	3-1
3-1-1 Facing holder	3-1
3-1-2 Boring bar holder	3-2
3-1-3 U-drill holder	3-3
3-1-4 Boring bar socket	3-4
3-1-5 Drill socket	3-5-E
4. PROGRAM CHART	4-1
4-1 Octagonal drum turret	4-1
4-1-1 Chuck work (by O.D. turning tool)	4-1
4-1-2 Chuck work (by I.D. turning tool)	4-3
4-1-3 Shaft work (projection of tool: 30 mm (1.25 in.)	4-5
4-1-4 Shaft work (projection of tool: 40 mm (1.75 in.)	4-7
4-2 12-side drum turret	4-9
4-2-1 Chuck work (by O.D. turning tool)	4-9
4-2-2 Shaft work	4-10
4-2-3 Chuck work (by I.D. turning tool)	4-11-E
5. CUTTING AREA	5-1
5-1 Octagonal drum turret	5-1
6. DIMENSTIONAL DRAWING OF TURRET	6-1
6-1 Octagonal drum turret (Standard)	6-1
7. DIMENSTIONAL DRAWING OF SPINDLE (JIS A2-5")	7-1