

MITSUBISHI

POWER SUPPLY UNIT G15F

OPERATION MANUAL

DESCRIPTION OF POWER SUPPLY UNIT G15F
AND MACHINING CHARACTERISTIC DATA
(F1 SERIES)

CONTENTS

	Page
1. GENERAL DESCRIPTION	1
(1) Features	1
(2) Basic configuration	2
2. OPERATION	3
(1) Nomenclature	3
(2) Pilot lamps	3
(3) Knobs on the operation panel	4
(4) Switches on the operation panel	5
(5) Meters on the operation panel	6
3. AUTOMATIC VOLTAGE REGULATOR	7
4. MACHINING CONDITION SETTING METHOD	8
(1) Voltage selector	8
(2) Power setting	8
(3) OFF time	8
(4) Stabilizer A	9
(5) Stabilizer B	9
(6) Mean machining voltage	9
(7) Wire tension, wire speed	10
(8) Dielectric fluid flow rate.....	10
(9) Meter relay	10
5. PRECAUTIONS IN MACHINING	11
(1) Initial condition setting	11
(2) Thickness difference of workpieces	11
(3) Others	12

MACHINING CHARACTERISTIC DATA

[SKD-11]	13
Wire electrode ϕ 0.15 mm (OB-15P)	14
Wire electrode ϕ 0.2 mm (OB-20P)	23
Wire electrode ϕ 0.25 mm (OB-25P)	36
Wire electrode ϕ 0.3 mm (OB-30P)	45
[COPPER]	54
Wire electrode ϕ 0.2 mm (OB-20P)	55
Wire electrode ϕ 0.25 mm (OB-25P)	68
Wire electrode ϕ 0.3 mm (OB-30P)	77
[HARD ALLOY]	86
Wire electrode ϕ 0.2 mm (OB-20P)	87
G15F POWER SUPPLY STANDARD FOR SETTING OF MACHINING CONDITION	96