

CNC SYSTEMS

OSP5020L
OSP500L-G

LB-II Series CNC Lathes

MAINTENANCE MANUAL (1st Edition)

TABLE OF CONTENTS

	<u>PAGE</u>
SECTION 1 OUTLINE OF OSP5020L/OSP500L-G	1
1. Special Features of OSP5020L/OSP500L-G	1
SECTION 2 SUMMARY OF OPERATION	2
SECTION 3 STRUCTURE OF OSP5020L/OSP500L-G	3
1. CPU and Power Supply Unit	3
2. Servo Drive Unit	3
3. Relay and Magnet Switch Circuits	3
4. Spindle Drive VAC Motor Control	4
5. Control Enclosure	4
6. Operation Panel	4
7. Absolute Position Feedback Encoders	4
8. Cooling Unit	4
9. Turret Control	4
SECTION 4 MAINTENANCE AND INSPECTION	5
1. Inspection during Installation	5
1-1. Installation Site	5
1-2. Environmental Requirements	5
1-3. Power Supply Voltage Inspection	6
2. Periodical Inspection	6
3. Operation and Structure of the CNC	7
3-1. Example of Operation	7
3-2. Description on Each Major CNC Unit	8
4. Self-Diagnostics	10
4-1. Alarm Display and Error Display	10
4-2. Check Data Display	10

	<u>PAGE</u>
SECTION 5 TROUBLE AND TROUBLESHOOTING	34
1. Analysis of Trouble	35
2. Machine-Mounted Electricals	36
2-1. Inspection of Limit Switches (Check Method by Multi-Meter)	37
2-2. Inspection of Limit Switches and Proximity Switches Using Self-diagnostic Function	38
3. Inspection of Position Encoder	39
4. CPU	40
4-1. Operation and Structure of the CPU	40
4-2. Checking CPU Operations	40
4-3. Loading Control Software through Floppy Disk	43
4-4. CPU Power Supply	47
5. Relay and Magnet Switch Circuits	49
5-1. Operation and Structure of a Relay and Magnet Switch Circuit	49
5-2. Inspection of Relays and Magnet Contactors	50
6. Cooling Unit	53
6-1. Maintenance and Inspection	53
SECTION 6 MAINTENANCE OF COMPONENTS	54
1. Brushless Servomotor Drive Unit (BL-D**A Series)	54
1-1. Outline	54
1-2. Configuration of BL-D**A	54
1-3. Construction	56
1-4. Protection and Alarm Monitoring Function	58
1-5. Trouble and Troubleshooting	60
1-6. Checking Power Transistor	65

	<u>PAGE</u>
2. Spindle Drive Unit for VAC II Motor (Okuma Make)	67
2-1. Outline	67
2-2. Configuration and Construction	68
2-2-1. Configuration	68
2-2-2. Construction	69
2-2-2-1. Major Component Parts Arrangement	70
2-3. Operation Status Indication	77
2-3-1. Control PCB Operation Status Indicating Lamps	77
2-3-2. Operation Status Indicating Lamps	78
2-3-2-1. Normal Operation Status Indication	79
2-3-2-2. Failure Operation Status Indication	80
2-4. Troubleshooting	88
2-4-1. Confirmation of Power Supply and Connectors	88
2-4-2. Trouble and Troubleshooting	89
2-4-3. Recovery from Failure Status	107
2-5. Inspection and Maintenance	108
2-5-1. Instruments and Parts Used for Maintenance	108
2-5-2. Inspection and Replacement Procedure for Semi-conductor Devices	110
2-5-2-1. Transistor Module Inspection Procedure	110
2-5-2-2. Base Circuit Transistor Inspection Procedure	112
2-5-2-3. Diode Module Inspection Procedure	112
2-5-2-4. Procedure to Replace Main Circuit Semi-conductor Devices	115
2-5-3. Fuse Replacement	116
2-5-3-1. Fuse Blown Condition	116
2-5-3-2. Inspection and Replacement Procedure for Fuses	117
2-5-3-3. Fuse Rating	119
2-5-4. Replacing Control PCB and Power Supply Unit	119
2-5-4-1. Control PCB Replacement Procedure	119
2-5-4-2. Power Supply Unit Replacement Procedure	122

	<u>PAGE</u>
3. PCB Type Relay Panel	124
3-1. Arrangement Drawings	124
3-2. Construction	127
4. Model 2702 Tape Reader	131
4-1. Outline	131
4-2. Specifications	131
4-3. Preparation	133
4-4. Maintenance	135
SECTION 7 ELECTRICAL SPARE PARTS LIST	138
SECTION 8 POWER REQUIREMENTS	140
APPENDED DIAGRAMS	142