

SD1 CNC Drilling EDM



User's Manual

372350351/Ver. 04. 00/2005.01

ACTSPARK 

Beijing Agie Charmilles Industrial Electronics Co., Ltd.
Mapo Town, Shunyi District, Beijing 101300, P. R. China
Tel.: +86 10 6940 4615 Fax: +86 10 6940 2288
E-mail: info@actspark.cn www.actspark.cn

Agie Charmilles Group
+GF+

Contents

- C1. Safety Instructions
- C2. Installation
- C3. User Interface
- C4. Operation
- C5. Parameters
- C6. Application Examples
- C7. Maintenance
- C8. Wear Parts and Consumables
- C9. Block Diagrams
- Appendix 1. Error Message
- 2. Options

All rights reserved. No part of this publication may be reproduced in any form or by any means, electronic or mechanical, including photocopying, recording, or by any other information storage and retrieval system, without permission in writing from Beijing AGIE Charmilles.
Note: The technical data and illustrations are not binding. They are subject to change without prior notice.

SD1 User's Manual

Contents

1	Technical data	3
2	Packing and handling	4
	2.1 Packing	4
	2.2 Transport and lifting	5
	2.3 Unpacking and handling	6
3	Installation	9
	3.1 Environment	9
	3.2 Floor space	9
	3.3 Unblocking of the table	10
	3.4 Leveling of the machine	10
	3.5 Electric connection	11
	3.6 Mechanical connection	11
4	Commissioning	12
	4.1 Check prior to switching on	12
	4.2 Switch on	13

SD1

C2. Installation

Contents

1	Introduction of machine	3
1.1	Structure	3
1.2	High pressure pump	4
2	Interface introduction	5
3	MANU window	7
4	Setup window	8
5	Manching Conditions Window	10
6	EDIT Window	11
7	Introduction of functions	14
7.1	System functions	14
7.2	Special functions F00-F99	14
7.3	Coordinate system and movement direction	16
7.4	Electric unit	17

SD1

C3. User Interface

Contents

1	Clamping and installation	3
1.1	Clamping workpiece	3
1.2	Installing of the tubular electrode.....	3
2	Operation	4
2.1	Switching on	4
2.2	Switching off	5

SD1 C4. Operation

Contents

Abbreviations.....	2
1 Machining conditions table (Metric).....	3
1.1 Work-piece: steel (Cr12)	
Tubular electrode: brass.....	3
1.2 Work-piece: 1Cr18Ni9Ti	
Tubular electrode: brass.....	5
1.3 Work-piece: aluminum	
Tubular electrode: brass.....	7
1.4 Work-piece: carbide YG6	
Tubular electrode: copper.....	9
1.5 Work-piece: carbide YG8	
Tubular electrode: copper.....	10
1.6 Work-piece:brass	
Tubular electrode: copper.....	11
1.7 Work-piece: copper	
Tubular electrode: copper.....	13
2 Machining conditions table (Inch).....	15
2.1 Work-piece: steel (Cr12)	
Tubular electrode: brass.....	15
2.2 Work-piece: 1Cr18Ni9Ti	
Tubular electrode: brass.....	17
2.3 Work-piece: aluminum	
Tubular electrode: brass.....	19
2.4 Work-piece: carbide YG6	
Tubular electrode: copper.....	21
2.5 Work-piece: carbide YG8	
Tubular electrode: copper.....	22
2.6 Work-piece: brass	
Tubular electrode: copper.....	23
2.7 Work-piece: copper	
Tubular electrode: copper.....	25

SD1

C5. Parameters

Contents

1	Single point machining.....	3
2	Positioning movement.....	6
3	Automatic machining of multi-hole	8

SD1 **C6. Application Examples**

Contents

1	Daily maintenance	3
1.1	Check of filter screen	3
1.2	Locations of lubrication	3
1.3	Cleaning of machine	4
2	Periodical maintenance	5
2.1	Check the machine at every half-yearly	5
3	Adjusting, maintenance of the high pressure pump	6
4	Wearing parts displacement	6
5	Machine status	7

SD1 C7. Maintenance

Contents

1	Wear parts.....	3
2	Consumables	3

SD1 **C8. Wear parts and Consumables**

Contents

- 1 Mechanical block diagrams
- 2 Electric block diagrams

SD1

C9. Block Diagrams

Contents

1	Main machine 1/2.....	1
2	Main machine 2/2.....	2
3	Table 1/ 2.....	3
4	Table 2/ 2.....	4
5	X-axis drive system.....	5
6	Y-axis drive system.....	6
7	X-axis guide lateral pre-tension system.....	7
8	Y-axis guide lateral pretension system.....	8
9	Column.....	9
10	Z-axis drive system.....	10
11	W- axis drive system.....	11
12	Rotary spindle.....	12
13	Reservoir.....	13
14	High pressure pump.....	14

SD1

Block Diagrams

[Mechanical]

Content

1	System block diagram.....	1
2	Schematic diagram 1/ 2.....	2
3	Schematic diagram 2/ 2.....	3
4	System internal connection drawing.....	4
5	Machine connection drawing.....	5
6	Mother- board bus diagram.....	6
7	Main control system Schematic diagram.....	7
8	Control system schematic diagram.....	8
9	BPR-B01 pulse generating board Schematic diagram.....	9
10	STB-B32 relay board schematic diagram.....	10
11	IMC-B06X-axis motor drive.....	11
12	GPM - B51 power board schematic diagram.....	12
13	Meanings of indicated lights.....	13

SD1

Block Diagrams

[Electric]

Contents

1 Error message3

SD1 Appendix 1: Error message

Contents

1 Options 3

SD1 Appendix2: Options