

CNC SYSTEMS

**OSP5020L**

**OSP5000L-G**

**OSP500L-G**

---

---

---

**GAUGING MANUAL (5th Edition)**

## TABLE OF CONTENTS

	<u>PAGE</u>
PART I AUTOMATIC WORK GAUGING & TOUCH SETTER M/A .....	1
SECTION 1 AUTOMATIC WORK GAUGING .....	1
1. OUTLINE OF AUTOMATIC WORK GAUGING SYSTEM .....	2
1-1. OUTLINE .....	2
1-2. CONFIGURATION .....	2
1-3. GAUGING PRINCIPLE .....	3
2. PROGRAMMING .....	6
2-1. PROGRAMMING FORMAT FOR A MODEL NOT FEATURING TOOL LIFE MANAGEMENT .....	6
2-1-1. One-Saddle (1S) Specification .....	6
2-1-2. Two-Saddle (2S) Specification .....	7
2-2. PROGRAMMING FORMAT FOR A MODEL FEATURING TOOL LIFE MANAGEMENT .....	8
2-2-1. One-Saddle (1S) Specification .....	8
2-2-2. Two-Saddle (2S) Specification .....	10
3. MASTER RING GAUGING CYCLE PROGRAM .....	12
3-1. MASTER RING GAUGING CYCLE - ID .....	12
3-2. MASTER RING GAUGING CYCLE - OD .....	13
3-3. GAUGING CYCLE G30 .....	14
3-4. GAUGING CYCLE SUBPROGRAMS .....	15
3-4-1. ORGIA .....	15
3-4-2. ORGOA .....	19
3-4-3. ORNGB .....	20
3-5. MASTER RING GAUGING PROGRAM FOR MODELS FEATURING TOOL LIFE MANAGEMENT .....	21
3-6. MASTER RING GAUGING CYCLE "START" CONDITIONS .....	22
4. WORK GAUGING CYCLE PROGRAM (RADIUS GAUGING PROGRAM) .....	23
4-1. WORK GAUGING CYCLE .....	23
4-2. GAUGING CYCLE SUBPROGRAMS .....	24
4-2-1. OWMXA .....	24
4-2-2. OWMZA .....	28
4-2-3. OWXBA .....	29
4-2-4. OWXBB .....	29
4-2-5. OWZBA .....	30
4-2-6. OWZBB .....	30

	<u>PAGE</u>
4-3. WORK GAUGING PROGRAM FOR A MODEL FEATURING TOOL LIFE MANAGEMENT ....	32
4-3-1. Differences from Gauging Cycle for the Control Not Featuring Tool Life Management .....	32
4-3-2. Additional Functions for the Control Featuring Tool Life Management .....	35
4-4. CONDITIONS FOR WORK GAUGING CYCLE EXECUTION .....	37
4-5. TRIAL CUT GAUGING CYCLE PROGRAM .....	38
4-6. CONDITIONS FOR STARTING TRIAL CUT GAUGING CYCLE .....	40
5. DIAMETER GAUGING CYCLE PROGRAM (IN-PROCESS WORK GAUGING) .....	42
SECTION 2 TOUCH SETTER CYCLE M/A .....	60
1. AUTOMATIC TOOL GAUGING CYCLE BY TOUCH SETTER .....	61
1-1. OUTLINE OF TOUCH SETTER .....	61
1-1-1. Outline .....	61
1-1-2. Construction .....	61
1-1-3. Gauging Principle .....	62
1-2. PROGRAMMING FORMAT - TOUCH SETTER A SPECIFICATION .....	63
1-2-1. Programming Format For A Model Not Featuring Tool Life Management .....	63
1-2-2. Programming Format For A Model Featuring Tool Life Management ..	65
1-3. OPERATIONS .....	67
1-3-1. Sensor Head .....	67
1-3-2. Sensor Touch Position .....	70
1-3-3. Basic Axis Movements .....	72
1-4. TOUCH SETTER INTERLOCK .....	76
1-5. AUTOMATIC TOUCH SETTER GAUGING CYCLE PROGRAM .....	77
1-5-1. Tool Offset Data Read-out Cycle .....	77
1-5-2. Tool Breakage Detection Cycle .....	81
1-5-3. Example Of Program - Two-saddle Specification .....	82
1-5-4. Tool Gauging Program For A Model Featuring Tool Life Management .....	83
1-5-5. Conditions For Automatic Touch Setter Gauging Cycle Execution ..	85
2. TOUCH SETTER MANUAL GAUGING CYCLE .....	88
2-1. OUTLINE .....	88
2-2. MANUAL TOUCH SETTER GAUGING CYCLE .....	89
2-3. AUTOMATIC SETTING OF DATA .....	92
2-4. PARAMETER SETTING .....	95

	<u>PAGE</u>
SECTION 3 SUBPROGRAMS OTHER THAN GAUGING CYCLES .....	96
1. GAUGING CYCLE START CONDITION COUNTER (SUBPROGRAM OCNCK) .....	97
2. RESETTING GAUGING CYCLE START CONDITIONS (SUBPROGRAM OMSSF) .....	99
3. EVALUATION OF TRIAL CUT GAUGING CYCLE FOR AUTOMATIC TOOL SELECTION (SUBPROGRAM OTRCK) .....	100
4. EVALUATION OF AUTOMATIC TOUCH SETTER GAUGING CYCLE START CONDITION (SUBPROGRAM OTST) .....	101
SECTION 4 DISPLAY OF GAUGING DATA .....	103
1. DISPLAY OF GAUGING DATA .....	104
SECTION 5 DATA SETTING .....	107
1. MASTER RING POSITION DATA .....	109
2. SETTING COUNTER FOR GAUGING CYCLE ON CONDITION .....	110
3. SETTING OPTIONAL PARAMETER (BIT) DATA .....	112
3-1. GAUGING CYCLE ON PUSHBUTTON SETTING HOLD BIT .....	113
3-2. GAUGING CYCLE PROGRAM DISPLAY BIT .....	114
4. FEEDRATE IN GAUGING CYCLES .....	115
SECTION 6 CAUTIONS .....	116
SECTION 7 APPENDIX .....	117
1. ALARM TABLE .....	117
2. CONTROL STATEMENTS .....	123
2-1. GOTO STATEMENT .....	124
2-2. IF STATEMENT .....	125
2-3. EVALUATION OF DEFINED OR UNDEFINED LOCAL VARIABLES BY IF STATEMENT .....	126
2-4. CALL STATEMENT .....	127
2-5. RTS STATEMENT .....	128
2-6. CONTINUATION CODE .....	129

	<u>PAGE</u>
PART II AUTOMATIC ZERO OFFSET .....	130
1. OUTLINE .....	130
2. OPERATIONS .....	130
2-1. GAUGING CYCLE IN SINGLE-CONTACT MDOE .....	130
2-2. GAUGING CYCLE IN DOUBLE-CONTACT MODE .....	131
3. GAUGING CYCLE SUBPROGRAMS .....	
3-1. SUBPROGRAM OZOFA .....	133
3-2. SUBPROGRAM OZOFB .....	134
4. PROGRAMMING .....	135
4-1. SINGLE-SADDLE MODEL .....	135
4-2. TWO-SADDLE SPECIFICATION .....	135
 PART III POST-PROCESS AUTOMATIC WORK GAUGING - 5-GRADE SIGNAL SYSTEM .....	 136
1. SYSTEM OUTLINE .....	136
1-1. SUMMARY .....	136
1-2. SYSTEM LAYOUT .....	136
2. AUTO COMPENSATION OF TOOL OFFSET VALUE .....	138
2-1. GAUGING LAG (NO. OF WORKPIECES) .....	138
2-2. COMPENSATION TIMING .....	138
2-3. COMPENSATION PROCESS .....	139
2-4. COMPENSATION INVALID (IGNORE) .....	140
2-5. COMPENSATION AFTER TOOL AUTO INDEXING .....	142
3. AUTO COMPENSATION DATA SETTING AND DISPLAY .....	144
3-1. DATA SETTING METHOD .....	144
3-2. DATA SETTING RANGE .....	146
3-3. AUTO CORRECTION DATA DISPLAY .....	147
4. PROGRAM .....	148
5. POST-PROCESS GAUGING DATA INPUT .....	149
6. ALARMS AND MESSAGES .....	153

	<u>PAGE</u>
PART IV POST-PROCESS AUTOMATIC WORK GAUGING - 7-GRADE SIGNAL SYSTEM .....	154
1. SYSTEM OUTLINE .....	154
1-1. SUMMARY .....	154
1-2. SYSTEM LAYOUT .....	154
1-3. BASIC PRINCIPLES .....	154
2. AUTO COMPENSATION OF TOOL OFFSET VALUE .....	156
2-1. GAUGING LAG (NO. OF WORKPIECES) .....	156
2-2. COMPENSATION TIMING .....	156
2-3. COMPENSATION PROCESS .....	157
2-4. COMPENSATION INVALID (IGNORE) .....	158
2-5. CORRECTION AFTER TOOL AUTO INDEXING .....	160
3. AUTO COMPENSATION DATA SETTING AND DISPLAY .....	162
3-1. DATA SETTING METHOD .....	162
3-2. DATA SETTING RANGE .....	164
3-3. AUTO COMPENSATION DATA DISPLAY .....	165
4. PROGRAM .....	166
5. POST-PROCESS GAUGING DATA INPUT .....	167
6. ALARMS AND MESSAGES .....	171

	<u>PAGE</u>
PART V AUTOMATIC WORK GAUGING & TOUCH SETTER M/A SOFTWARE .....	172
1. OUTLINE OF GAUGING CYCLES .....	172
2. VARIABLE TABLES .....	173
2-1. COMMON VARIABLES (V901 - V932) .....	174
2-2. SYSTEM VARIABLES 1 .....	177
2-3. SYSTEM VARIABLES 2 .....	180
2-4. SYSTEM VARIABLES 3 .....	181
2-5. SYSTEM VARIABLES 4 .....	183
2-6. INPUT/OUTPUT VARIABLES .....	186
3. PRINT COMMAND .....	188
3-1. PRINT OUT DATA .....	189
3-2. PRINT FORMAT .....	190
4. NOTES .....	193
4-1. NOEX .....	193
4-2. IF STATEMENT USED FOR JUDGING WHETHER LOCAL VARIABLES HAVE BEEN DEFINED OR NOT .....	194
4-3. CALCULATION OF MEASURED VALUE (SENSOR CONTACT POSITION ON PROGRAM COORDINATE SYSTEM) IN GAUGING CYCLE IN Z-AXIS .....	195
5. SUBPROGRAM TABLE .....	196
6. FLOW CHART .....	199
7. LIST .....	227
8. APPLICATIONS OF MAKER SUBPROGRAMS (MSB) .....	243

	<u>PAGE</u>
PART VI AUTOMATIC ZERO OFFSET SOFTWARE .....	247
1. OUTLINE OF GAUGING CYCLE USED FOR ZERO OFFSET .....	247
2. VARIABLE TABLES .....	248
2-1. COMMON VARIABLES (V901 - V932) .....	249
2-2. SYSTEM VARIABLES 1 .....	251
2-3. SYSTEM VARIABLES 2 .....	252
3. NOTES .....	253
3-1. NOEX .....	253
3-2. IF STATEMENT USED FOR JUDGING WHETHER LOCAL VARIABLES HAVE BEEN DEFINED OR NOT .....	254
3-3. CALCULATION OF MEASURED VALUE .....	255
4. FLOW CHART .....	256
5. LIST .....	259
6. APPLICATIONS OF MAKER SUBPROGRAMS (MSB) .....	260
 PART VII POST-PROCESS AUTOMATIC WORK GAUGING SOFTWARE - 5-GRADE SIGNAL SYSTEM .....	 264
1. OUTLINE OF GAUGING CYCLE .....	264
2. VARIABLE TABLES .....	265
2-1. COMMON VARIABLES (V901 - V932) .....	266
2-2. SYSTEM VARIABLES 1 .....	268
2-3. SYSTEM VARIABLES 2 .....	270
2-4. INPUT/OUTPUT VARIABLES .....	271
3. PRECAUTIONS (FOR ALL MSB OPERATIONS) .....	272
4. FLOW CHART .....	273
5. LIST .....	277
6. APPLICATIONS OF MAKER SUBPROGRAMS (MSB) .....	279

	<u>PAGE</u>
PART VIII POST-PROCESS AUTOMATIC WORK GAUGING SOFTWARE	
- 7-GRADE SIGNAL SYSTEM .....	283
1. OUTLINE OF GAUGING CYCLE .....	283
2. VARIABLE TABLES .....	283
2-1. COMMON VARIABLES (V901 - V932) .....	285
2-2. SYSTEM VARIABLES 1 .....	287
2-3. SYSTEM VARIABLES 2 .....	289
2-4. INPUT/OUTPUT VARIABLES .....	290
3. PRECAUTIONS (FOR ALL MSB OPERATIONS) .....	291
4. FLOW CHART .....	291
5. LIST .....	296
6. APPLICATIONS OF MAKER SUBPROGRAMS (MSB) .....	298

Note: To avoid any confusion over the use of the letter "O (oh)" and figure "0 (zero)" in this manual, the numerical value "0 (zero)" is expressed as "ø" if there is any possibility of misunderstanding.