

Interactive Manual Data Input Function

ONE-TOUCH IGF

OSP5020L CNC SYSTEM

OPERATION MANUAL -APPLICATION-
(3rd Edition)

TABLE OF CONTENTS

	<u>PAGE</u>
PART I APPLICATION	1
SECTION 1 STARTING-UP ONE-TOUCH IGF SYSTEM	1
1. Selection of One-touch IGF Mode	1
2. Turning On Graphic Edit Function	3
SECTION 2 STANDARD HOLE DATA SETTING	6
1. What is the Function of Standard Hole Data Setting?	6
2. Standard Hole Data Setting Procedure	8
3. Items to be Set as Standard Hole Data	10
SECTION 3 TOOL DATA SETTING	15
1. What is the Function of Tool Data Setting?	15
2. Tool Data Setting Procedure	17
3. Items to be Set as Tool Data	21
SECTION 4 MATERIAL DATA SETTING	32
1. What is the Function of Material Data Setting?	32
2. Material Data Setting Procedure	34
3. Items to be Set as Material Data	37
SECTION 5 ONE-TOUCH IGF PARAMETER SETTING	46
1. What is the Function of an IGF Parameter?	46
2. Parameter Setting Procedure	48
3. One-touch IGF Parameters	50
SECTION 6 FINISHED SHAPE DEFINITION (SHAPE DEFINITION)	78
1. What is the Function of "Finished Shape Definition"?	78
2. Basic Blank Shape Definition (Designation of blank material, basic blank material shape (outline of blank material shape), and type of blank material shape)	79
3. TURNING MACH SHAPE Definition	82
4. Finished Shape Definition for Multiple Machining (optional)	126
5. SIDE GENERATING SHAPE Definition	153
6. FACE GENERATING SHAPE Definition (optional)	166

	<u>PAGE</u>
SECTION 7 BLANK MATERIAL SHAPE DEFINITION (SHAPE DEFINITION)	181
1. What is the Function of "Blank Material Shape Definition"?	181
2. AVE. BLANK SHAPE Definition	183
3. BLANK SHAPE Definition	188
SECTION 8 SETUP INPUT	198
1. What is the Function of "Setup Input"?	198
2. Designating Bar Material Preparation (bar feeder (puller) specification)	200
3. CHUCK-CENTER Definition	200
SECTION 9 AUTOMATIC PROCESS DETERMINATION	203
1. What is the Function of "Automatic Process Determination"?	203
2. Determination of Machining Area	206
3. Determination of Machining Method	207
4. Role of the Condition Setting Function	211
4-1. Functions	211
5. Data Setting Item	213
6. Automatic Process Determination Using the Condition Setting Function	233
SECTION 10 PROCESS TEST	234
1. What is the Function of "Process Test"?	234
2. Test	235
SECTION 11 PROCESS EDIT	245
1. What is the Function of "Process Edit"?	245
2. Checking the Contents of Process (Process Check Screen)	248
3. Editing the Process in Unit	252
4. Editing the Machining Method (turning, special machining)	264
5. Editing the Machining Method (optional: multi-machining specification, contour generating machining specification)	275
6. Process List Display	282

	<u>PAGE</u>
7. Editing the Finished Shape (rough turning, copying, finish turning)	287
7-1. Selection of Process to be Edited	287
7-2. Motion from Cycle Reference Point to Infeed Point	297
7-3. Motion at the End Point	298
7-4. Starting and End Points for Rounding (R-CHF) and Chamfering	299
7-5. Deleting the Edited Data	301
7-6. Switching to the MACH. METHOD AMEND Screen	301
7-7. Terminating the Machining Shape Editing	301
8. Editing the Finished Shape (special turning)	302
8-1. Selection of Process to be Edited	302
8-2. Deleting the Edited Data	309
8-3. Switching to the MACH. METHOD AMEND Screen	309
8-4. Terminating the Machining Shape Editing	309
9. Editing the Finished Shape (multi-machining) (optional: multi-machining specification)	310
9-1. Selection of Process to be Edited	310
9-2. Deleting the Edited Data	313
9-3. Switching to the MACH. METHOD AMEND Screen	313
9-4. Terminating the Machining Shape Editing	313
10. Tool Path Control	314
10-1. Approach and Retract of Cutting Tool	314
10-2. Tool Path Control	315
11. Process Test	316
12. Editing the NC Program	317
13. Editing the Gauging Process (Optional: in-process gauging specification)	318
14. Machining Kind (Process Kind) List	319
SECTION 12 PART PROGRAM CREATION	322
1. What is the Function of "Part Program Creation"?	322
2. Program Creating Procedure	323
3. Sequence Numbers and Sequence Names	325
4. Output of Modal M Codes	326
5. Automatic Generation of Optional Stop (M01)	327
6. Spindle Control	327
7. Coolant On/Off Control	328
8. Tool Change Control	328

	<u>PAGE</u>
SECTION 13 TERMINATION OF ONE-TOUCH IGF OPERATION	334
SECTION 14 DATA INPUT USING MATH OPERATION	335
1. Arithmetic and Function Operation Symbol	335
2. Input Examples	337
SECTION 15 DATA INPUT USING ADDITION FUNCTION	338
SECTION 16 ONE-TOUCH IGF TEMPORARY QUIT AND RECOVERY FUNCTION	339
SECTION 17 ANIMATION DATA	341
1. What is the Function of "Animation Data"?	341
1-1. Tool Shape Definition	341
1-2. Chuck Barrier Definition	343
1-3. Tailstock Barrier Definition	343
2. Drawing Blank Shape	344
2-1. Definition Format	344
2-2. User Graphic Commands (UGC)	345
SECTION 18 ONE-TOUCH IGF FOR PRECISION LATHES (OPTIONAL)	354
1. Unit System	354
2. Upper and Lower Limits of Data Setting for Process Edit, Tool Data Set and Parameter Set (Dimension parameter)	355
3. Material Data	356
SECTION 19 BAR FEEDER AND BAR PULLER FUNCTION (OPTIONAL)	357
1. Bar Material Preparation Parameters	357
2. Designating Bar Material Preparation Parameter	360

	<u>PAGE</u>
SECTION 20 ONE-TOUCH IGF ON IN-PROCESS GAUGING FUNCTION SPECIFICATION (OPTIONAL)	368
1. Parameters Used for Gauging Cycles	368
2. Making Gauging Processes	369
2-1. Gauging Cycles for Rough, Turning, Finish Turning, and Copy Processes ...	369
2-2. Gauging Cycle for Grooving Process	375
3. Process Edit Operation Precautions	378
4. Gauging Process Test	378
5. NC Gauging Process Program	379
SECTION 21 ONE-TOUCH IGF WITH LOAD MONITOR SPECIFICATION (OPTIONAL)	381
1. Setting Monitor Axis	381
2. Others	383
SECTION 22 ONE-TOUCH IGF WITH ATC SPECIFICATION (OPTIONAL)	384
SECTION 23 CONVERSION FUNCTION (OPTIONAL)	385
1. Operating Procedure	385
2. Items to be Converted	388
PART II ERROR LIST	393