

PHL-200 RINK MOTION PRESS

INSTRUCTION MANUAL

MARCH 1995

P A T E C

PRESS AUTOMATION TECHNOLOGY PTE. LTD.

- CONTENTS -

BEFORE PRESS OPERATION

1. FEATURES OF PATEC LINK PRESS
2. SPECIFICATIONS AND DIMENSIONS
 - 2-1 SPECIFICATIONS AND DIMENSIONS
 - 2-2 PRESS GENERAL VIEW
 - 2-3 PRESS STROKE CURVE
 - 2-4 ENERGY CURVE
 - 2-5 DIE SPACE
3. OPERATION
 - 3-1 ELECTRIC CONTROL
 - * PRECAUTION FOR SAFTY OPERATION
 - * PRESS OPERATION
 - * ELECTRIC DIAGRAM
 - 3-2 LUBLICATIONS LUBRICATIONS
POINTS
 - 2-1 LUBLICATIONS ON THE MAKER
 - 3-3 DROWING
 - * PRESS OPERATION DIAGRAM
 - * GREASE PIPING DIAGRAM
 - * ELECTRIC PARTS
 - 3-4 SPARE PARTS LIST
 - * CLUTCH AND BRAKE PARTS
 - * PACKING , O-RING
4. MAINTENANCE AND CHECK POINTS