

WIRE-CUT EDM SYSTEMS

H

Series

**INSTALLATION,
MAINTENANCE
AND
INSPECTION**

CONTENTS

1. WIRE-CUT EDM SYSTEM.....	1-1
1.1 Configuration.....	1-1
1.2 Specifications.....	1-2
1.2.1 Machine unit.....	1-2
1.2.2 Power supply unit.....	1-4
1.2.3 Controller.....	1-4
1.3 Installation.....	1-12
1.3.1 Installation layout.....	1-12
1.3.2 Installation location and precautions.....	1-12
1.3.3 Power supply.....	1-13
2. MACHINE UNIT MECHANICAL COMPONENTS.....	2-1
2.1 Names and functions.....	2-1
2.1.1 DWC90.....	2-1
2.1.2 DWC110.....	2-2
2.1.3 DWC200.....	2-3
2.1.4 DWC300.....	2-4
2.2 Operating procedure.....	2-5
2.2.1 Wire installation.....	2-5
2.2.2 Mounting workpiece.....	2-9
2.2.3 Lower wire guide cleaning.....	2-10
2.2.4 Power feed die replacement.....	2-10
2.2.5 Diamond die installation.....	2-10
2.2.6 Dielectric fluid injection.....	2-10
2.2.7 Perpendicular adjustment.....	2-10
2.2.8 Upper splash guard installation.....	2-11
2.2.9 Auxiliary hose handling.....	2-12
2.2.10 Z-axis clamp.....	2-13
2.2.11 Mounting large workpiece.....	2-18
2.2.12 Using positioning pins (accessories for DWC110, DWC200 and DWC300).....	2-20
2.2.13 Figure check before machining.....	2-20
2.3 Peripheral technique.....	2-21
2.3.1 Jigs.....	2-21
2.3.2 Preparing workpiece.....	2-23
2.3.3 Heat treatment of the workpiece for wire-cut electrical discharge machining.....	2-24
2.3.4 Processing distortion with wire-cut electrical discharge machining.....	2-25
2.3.5 Working of water in EDM operation.....	2-28
2.3.6 Cause of wire breakage.....	2-30
2.3.6.1 In the case of inappropriate process conditions.....	2-30
2.3.6.2 In the case of improper fluid pouring.....	2-31
2.3.6.3 Due to fluctuation in the wire tension.....	2-33
2.3.6.4 Due to a defective wire.....	2-33
2.3.6.5 Due to defective workpiece material.....	2-34
2.3.7 Avoiding processing fluid splash.....	2-36
2.4 Mechanical accessories.....	2-38
2.4.1 DWC90 mechanical accessories.....	2-38
2.4.2 DWC110 mechanical accessories.....	2-40
2.4.3 DWC200 mechanical accessories.....	2-42
2.4.4 DWC300 mechanical accessories.....	2-44
2.5 Wire collection box.....	2-46
2.5.1 Outline.....	2-46
2.5.2 Wire collection box configuration.....	2-46
2.5.3 About the wire collection box function.....	2-48
2.5.4 Maintenance check.....	2-49
2.5.5 Maintenance parts list.....	2-50

3.	DIELECTRIC FLUID RESERVOIR.....	3-1
3.1	Names of major components	3-1
3.2	Dielectric fluid feeder operation	3-3
3.2.1	Dielectric fluid resistivity adjustment	3-3
3.2.2	Handling rust inhibited dielectric fluid	3-6
3.3	Test machining.....	3-7
3.3.1	Dielectric fluid replenishment	3-9
3.3.2	Filter element replacement	3-10
3.3.3	Water drainage (to prevent freezing).....	3-12
4.	POWER SUPPLY UNIT G25C.....	4-1
4.1	Overview.....	4-1
4.1.1	Features.....	4-1
4.1.2	Basic configuration.....	4-1
4.2	Operation.....	4-2
4.2.1	Names of control panel components.....	4-2
4.2.2	Indicator lamps.....	4-3
4.2.3	Machining conditions.....	4-3
5.	CONTROLLER.....	5-1
5.1	System configuration.....	5-1
5.1.1	Configuration of controller.....	5-1
5.1.2	System loading.....	5-2
5.2	CRT setting and display unit configuration	5-6
5.2.1	Configuration.....	5-6
5.2.2	Keys and indicators.....	5-7
5.2.3	NC-operation status display area.....	5-14
5.2.4	Backlash input.....	5-17
5.2.5	Pitch error compensation	5-21
5.2.6	Maintenance and inspection.....	5-24
5.3	Manual box function.....	5-33
5.4	Handling of tape reader	5-36
5.4.1	Tape reader (option)	5-36
5.4.2	Tape case.....	5-40
5.5	Optional tape winder operation.....	5-41
5.5.1	Tape handling	5-41
5.5.2	Operation.....	5-45
	APPENDIX 1 Alarm contents	5-47
6.	MAINTENANCE, INSPECTION AND CONSUMABLES OF MACHINE UNIT	6-1
6.1	Maintenance and inspection.....	6-1
6.1.1	Daily checking.....	6-1
6.2	Lubrication table.....	6-4
6.2.1	DWC90.....	6-4
6.2.2	DWC110, 200, 300.....	6-5
6.2.3	Maintenance and inspection of XY drive motor	6-8
6.3	Maintenance/inspection of the lower roller	6-11
6.3.1	Cleaning of the aspirator.....	6-11
6.3.2	Inspection of roller	6-12
6.4	Maintenance and inspection of wire guide.....	6-13
6.4.1	Changing contact position of power feeder die and replacement.....	6-13
6.4.2	Replacement/cleaning of diamond die	6-14
6.4.3	Cleaning of lower nozzle	6-14
6.5	Consumable list.....	6-16
7.	WIRE ELECTRODES.....	7-1
7.1	Wire electrodes.....	7-1

7.1.1	Special alloy wire (OB-H wire)	7-2
7.1.2	Special alloy wire (DDWT wire)	7-3
7.1.3	Special alloy wire (H-TAF wire)	7-4
7.1.4	Brass wire (OB-P wire)	7-5
7.1.5	Brass wire (DDWH wire)	7-6
7.1.6	Brass wire (SBS-H wire)	7-7
7.1.7	Copper wire (TC wire)	7-8
7.1.8	Tungsten wire	7-9
7.1.9	Molybdenum wire	7-10
7.1.10	Zinc coated wire	7-11
8.	RADIO FREQUENCY INTERFERENCE CAUSED BY WIRE-CUT EDM SYSTEM AND ITS PREVENTIVE MEASURES	8-1
8.1	Actual examples of radio frequency interference	8-1
8.2	Propagation route of radio frequency interference	8-3
8.3	Radio frequency interference caused by wire-cut EDM systems and installation conditions	8-4
8.4	How to prevent radio frequency interference	8-5
8.4.1	Selection of system installation location	8-5
8.4.2	Locating television receiver	8-5
8.4.3	Shield cover for machining bath	8-6
8.4.4	Shield room	8-7
8.4.5	Shielded room serving also as dustproof room (temperature controlled area)	8-14
8.4.6	Installation of line filter	8-16
8.5	Regulations related to radio frequency interference	8-20
8.6	Actual preparations of shielded room	8-21