

LAMCOR CORPORATION

10 Chenell Drive Concord NH 03301 Phone - (603) 647-6386 Fax - (603) 647-6388 E-Mail - "info@lamcor.com"

Mechanical Rebuild Report

Customer Information

Customer: Canam

Location: n-a

Customer Contact: Jake Daniels

Address: 44 Old Princeton Rd

Fitchburg, MA 01420

Telephone: (978) 343-4400

Distribution

Send Report to:

Copies to: Customer

Equipment Information

Beloit 24" Double-Disk Refiner

Beloit Shop Number D-2924 Lamcor Shop Number M-1563

Lamcor

Report Prepared by: AMK

Issue Date: June 5, 2018



Scope of rebuild:

The following is description of the work that was done on this refiner:

- 1. Disassembled refiner
- 2. Installed new rotating assembly with shaft, sleeve, bearings and seals (Can-Am supplied item)
- 3. Install new 24" rotating head (Can-Am supplied item)
- 4. Installed new packing
- 5. Install Stainless liner on #1 and #4 surface (all surfaces now lined)
- 6. Installed new Helicoils for plates
- 7. Repaired the eroded areas in the refining cavity
- 8. Machined the door surface on base and door
- 9. Replaced Gauge Panel
- 10. Replaced the thrust washers and bushings on the door hinges
- 11. Rebuilt adjusting mechanism with new worm shaft bearings and seals. New sliding head seals. New clutch parts and handwheel.
- 12. Rebuilt gearmotor.
- 13. Reassembled and trammed.
- 14. Supplied new bolts.
- 15. Primed and painted





