

**NC-EDM
SYSTEMS**

J

Series

(2nd version)

**MACHINING
CHARACTERISTICS
DATA BOOK**

CONTENTS

1.	WORKPIECE AND APPLICABLE ELECTRODE MATERIALS	2
1.1	Setting of electrode polarity (Transistorized power source)	3
1.2	How to use recommended machining condition data	5
2.	RECOMMENDED MACHINING CONDITION EXAMPLE CHART.....	24
a-1	Super low wear orbital conditions example.....	25
b-1	Low wear orbital conditions example (0.2%).....	30
c-1	Low wear orbital conditions example (0.5%).....	35
d-1	Low wear orbital conditions example (1.0%).....	40
e-1	Super low wear orbital processing condition example.....	44
f-1	Low wear orbital processing conditions example (0.2%).....	49
g-1	Low wear orbital processing conditions example (0.5%).....	54
h-1	Low wear orbital processing conditions example (1.0%).....	59
3.	RECOMMENDED MACHINING CONDITION EXAMPLE CHART.....	65
a-1	Ultra-low consumption oscillation machining example (Fine surface finishing).....	66
b-1	Electrode consumption (0.2%) oscillation machining example (Fine surface finishing).....	71
c-1	Electrode consumption (0.5%) oscillation machining example (Fine surface finishing).....	76
d-1	Electrode consumption (1.0%) oscillation machining example (Fine surface finishing).....	81
e-1	Ultra-low consumption oscillation machining example (Fine surface finishing).....	86
f-1	Electrode consumption (0.2%) oscillation machining example (Fine surface finishing).....	91
g-1	Electrode consumption (0.5%) oscillation machining example (Fine surface finishing).....	96
h-1	Electrode consumption (1.0%) oscillation machining example (Fine surface finishing).....	101

4.	TABLE OF RECOMMENDED WORK CONDITIONS.....	107
(1)	For G35 and G70 power supply	108
a-1	Ultra-low consumption oscillation conditions example (0.5% or less)	108
b-1	Ultra-low consumption oscillation conditions example (0.5%).....	112
c-1	Ultra-low consumption oscillation conditions example (1.0%).....	116
(2)	For G140 power supply	120
d-1	Ultra-low consumption oscillation conditions example (0.5% or less)	120
e-1	Ultra-low consumption oscillation conditions example (0.5%).....	123
5.	ELECTRODE REDUCTION TABLE.....	126
5.1	Electrode reduction table (Cu:St).....	127
5.2	Electrode reduction table (Gr:St)	152
5.3	Master pack list.....	177
	Cu:St (10 μ Rmax).....	177
	Cu:St (10 μ Rmax).....	178
	Cu:St (15 μ Rmax).....	179
	Cu:St (15 μ Rmax).....	180
	Cu:St (2 μ Rmax)	181
	Cu:St (2 μ Rmax)	182
	Gr:St (15 μ Rmax).....	183
	Gr:St (25 μ Rmax).....	184
	Gr:St (45 μ Rmax).....	185
	Cu:Al (16 μ Rmax).....	186
	Cu:Al (8 μ Rmax)	187

Cu:Al (5 μ Rmax)	188
Cu:Al (3 μ Rmax)	189
6. MACHINING CHARACTERISTICS GRAPH.....	190
6.1 Machining characteristics graph (Cu:St).....	191
6.2 Electrode thickness to length wear ratio characteristics (Cu:St)	200
6.3 Corner wear characteristics by machining depth (Cu:St)	201
6.4 Machining characteries graph (Gr:St)	204
SDI MACHINING CONDITION DATA (C7).....	209
7.1 SDI Machining condition (C7).....	211
7.1.1 Machining condition pattern•Selective pattern	211
L9800 Cu-St Low wear machining.....	211
L9801 Cu-St Low wear machining – Mirror-surface machining (GM-10)	212
L9802 Cu-St Low wear machining – Mirror-surface machining (GM-1)	213
L9820 Gr-St Low wear machining.....	214
L9830 Cu•W-St High wear machining	215
L9831 Cu•W-Wc High wear machining	216
L9841 Ag•W-Wc High wear machining	217

Carbide: Amalgam Cu - W - WC : Co

7.1.2	Machining condition pattern •Selective pattern.....	218
L9850	Cu-St Low wear machining 6(5) → 2(3).....	218
L9851	Cu-St Low wear machining 5(5) → 2(3).....	219
L9852	Cu-St Low wear machining 4(5) → 2(3).....	220
L9853	Cu-St Low wear machining 6(5) → 1(4).....	221
L9854	Cu-St Low wear machining 5(5) → 1(4).....	222
L9855	Cu-St Low wear machining 4(5) → 1(3).....	223
L9856	Cu-St Low wear machining 3(5) → 1(2) – 6.0	224
L9857	Cu-St Low wear machining 3(2) → 1(2) – 3.5	225
L9858	Cu-St Low wear machining – Mirror-surface machining 3(2) → GM(1-1)	226
L9859	Cu-St Low wear machining 3(2) → SF(1-1).....	227
L9860	Cu-St Low wear machining 2(5) → 1(2) – 3.5	228
L9861	Cu-St Low wear machining 3(2) → 1(2) – 1.0	229
L9862	Cu-St Low wear machining – Mirror-surface machining 2(5) → GM(1-1).....	230
L9863	Cu-St Low wear machining – Mirror-surface machining 2(5) → SF(1-1)	231
7.2	Schedule of machining program.....	232
8.	E PACK LIST.....	233
8.1	Table for E pack directory regions	234
8.2	E pack.....	236