



LAMCOR CORPORATION

10 Chenell Drive
Concord NH 03301
Phone - (603) 647-6386
Fax - (603) 647-6388
E-Mail - "info@lamcor.com"

Mechanical Inspection Report

Customer Information

Customer: Canam

Location: n-a

Customer Contact: Jake Daniels

Address: 44 Old Princeton Rd

Fitchburg, MA 01420

Telephone: (978) 343-4400

Distribution

Send Report to:

Copies to: Customer

Equipment Information

Beloit 34" Double-Disk Refiner

Lamcor Shop Number M-1526

Lamcor

Report Prepared by: LS

Issue Date: January 21, 2018

Scope of rebuild:

The following is description of the work that was done on this refiner:

1. Disassembled refiner
2. Installed new rotating assembly with shaft, sleeve, bearings and seals (Can-Am supplied item)
3. Installed new packing
4. Install Stainless liner on #1 surface (all surfaces now lined)
5. Installed new Helicoils for plates
6. Repaired the eroded areas in the refining cavity and inlet/accept flanges
7. Machined the door surface
8. Replaced Gauge Panel
9. Replaced the thrust washers and bushings on the door hinges
10. Rebuilt adjusting mechanism with new worm shaft bearings and seals. New sliding head seals. New clutch parts and handwheel.
11. New gearbox (Can-Am supplied item) and rebuilt gearmotor.
12. Reassembled and trammed.
13. Supplied new bolts.
14. Primed and painted

