



LAMCOR CORPORATION

10 Chenell Drive
Concord NH 03301
Phone - (603) 647-6386
Fax - (603) 647-6388
E-Mail - "info@lamcor.com"

Mechanical Rebuild Report

Customer Information

Customer: Canam

Location: n-a

Customer Contact: Dan Nigrosh

Address: 44 Old Princeton Rd

Fitchburg, MA 01420

Telephone: (978) 343-4400

Distribution

Send Report to:

Copies to: Customer

Equipment Information

Beloit 38" Double-Disk Refiner

Lamcor Shop Number M-1831

Lamcor

Report Prepared by: AMK

Issue Date: August 21, 2026

Scope of rebuild:

The following is description of the work that was done on this refiner:

1. Disassembled refiner
2. Installed new sleeve, bearings and seals
3. Installed new packing
4. Installed new packing gland
5. Installed new Helicoils for plates
6. Installed 4500 series rotating head and spline
7. Machined the door surface on base and door
8. Replaced Gauge Panel
9. Replaced the thrust washers and bushings on the door hinges
10. Rebuilt adjusting mechanism with new worm shaft bearings and seals. New sliding head seals. New clutch parts and handwheel.
11. Rebuilt gearmotor.
12. Reassembled and trammed.
13. Primed and painted

