








TOLERANCES, EXCEPT AS NOTED:
 All dimensions in inches
 DECIMAL: .XX ±.015
 .XXX ±.005
 ANGLES: ±1°
 FRACTIONAL: DIMENSIONS ±.032
 HOLE DIA. ±.010



FW3200 SERVO WRAPPER
HIGH VOLTAGE PART-2
 SCALE FULL
 CAD FILE 320002602

DRAWN DK 12/15/08
 APPROVED
 DWG. NO. 3200-026
 SHEET 02
 REV. 0

REV.	DATE/INITIAL	DESCRIPTION
A		




REV.	DATE/INITIAL	DESCRIPTION
A		

TOLERANCES, EXCEPT AS NOTED:
All dimensions in Inches
DECIMAL: .XX ±.015
.XXX ±.005
ANGLES: ±1'
FRACTIONAL: DIMENSIONS ±.032
HOLE DIA. ±.010




WOODINVILLE, WASHINGTON, USA

FW3200 SERVO WRAPPER HIGH VOLTAGE PART-3		DRAWN DK 12/15/08	
*		APPROVED	
SCALE FULL		DWG. NO. 3200-026	0
CAD FILE 320002603		SHEET 03	REV.



TOLERANCES, EXCEPT AS NOTED: All dimensions in inches DECIMAL: .XX ±.015 .XXX ±.005 FRACTIONAL: DIMENSIONS ±.032 HOLE DIA. ±.010 ANGLES: ±1°			FORMOST FUJI WOODINVILLE, WASHINGTON, USA		FW3200 SERVO WRAPPER HIGH VOLTAGE PART-4 SERVO SERVO DRIVES		DRAWN DK 12/15/08 APPROVED DWG. NO. 3200-026 SHEET 04		0 REV.
SCALE FULL			CAD FILE 320002604						

REV.	DATE/INITIAL	DESCRIPTION
*		



TOLERANCES, EXCEPT AS NOTED:
All dimensions in inches

DECIMAL: .XX ±.015
.XXX ±.005
ANGLES: ±1°

FRACTIONAL: DIMENSIONS ±.032
HOLE DIA. ±.010

FORMOST FUJI
WOODINVILLE, WASHINGTON, USA

FW3200 SERVO WRAPPER
HIGH VOLTAGE WIRING – PART 5
CENTER SEAL

DRAWN DK 12/15/08

APPROVED

DWG. NO. 3200-026

SHEET 05

0
REV.

REV.	DATE/INITIAL	DESCRIPTION
------	--------------	-------------

