



NC High Speed Heavy Duty Carbide Circular Sawing Machine

CS-65W

INSTRUCTION MANUAL



MEGA MACHINE CO., LTD.

DOC NO : CS65W-100.U

CTRL NO : 06

UPDATE : 2004/04/19

DOC VER : A3

TABLE OF CONTENTS

	page
1.Safety declaration.....	7
1.1General operational precaution.....	7
1.2 The warning board.....	9
2.Introductory illustrations.....	10
2.1 Principal parts.....	10
2.2 Specifications:.....	11
3. Installation.....	12
3.1 Moving and lifting.....	12
4 Foundation layout and set-up:.....	13
4.1 Foundation.....	13
4.2 Leveling.....	14
4.3 Cleaning and oiling.....	15
4.4 Power source connection.....	15
5. Operation.....	16
5.1 Control panel.....	16
5.2 LCD panel illustration.....	18
5.2.1 LCD panel sequence	18
5.2.2 Panel sequence illustration	23
5.3 Operation process.....	25
5.4 Operation illustration.....	26
5.4.1 Preparation	26
5.4.2 Feed stroke setup	28
5.4.3 Circular saw blade speed RPM setup	29
5.4.4 Circular saw blade cutting feed rate setup	29
5.4.5 Oil mist lubricant adjusting	30
5.4.6 Add the oil mist lubricant	30
5.4.7 Oil mist lubricant device	31
5.4.8 Water lubricant adjusting	31
5.5 Pay more attention to below maintenance.....	32
6. Maintenance	33
6.1 Maintenance and inspection.....	33
6.2 Checking the brake lining wear	34
7. Hydraulic circuit and electric circuit.....	35
7.1 Hydraulic circuit	35
7.2 Electric circuit	36
7.3 Electric box case layout	49
8. Trouble shooting guide	50
9. Appendix(Cutting Data& Example).....	52