

Okamoto

CNC Precision Surface Grinding Machine

Instruction Manual

Type : PSG - 208DXNC

(FANUC-OMC 2-Axis Control)



OKAMOTO MACHINE TOOL WORKS, LTD.

A. Contents

A. Contents	I - II
-----------------------	--------

B. Specifications, PSG-208DXNC

[1] Main Unit	B1
[2] NC Unit	B3
[3] Accessories	B5
[4] Outline Drawing	B7
[5] Table Grinding Plane T-Slot, Detailed Drawing	B8

C. Installation

[1] Transportation	C1
[2] Cleaning	C1
[3] Installation, with Anchor Bolts	C2
[4] Foundation Drawing, with Anchor Bolts	C3
[5] Adjustment	C4

D. Oil Hydraulic Pressure and Lubrication

[1] Recommended Oil	D1
[2] Hydraulic Fluid Supply Method	D1
[3] Oil Hydraulic Equipment	D1
[4] Hydraulic Power Unit, Outline Drawing	D2
[5] Hydraulic Circuit Diagram and Parts List	D3
[6] Lubricating System	D5
[7] Oil Pressure Setting	D5
[8] Hydraulic Drive and Lubrication Adjustment	D6

E. Operation

[1] Control Panel, General	E1
[2] Control Panel, Layout	E8
[3] Control Panel, Manual Pulser	E9
[4] Tape Reader Connector	E10
[5] Stroke End Limit Switch	E10

F. Grinding Wheel

[1] Checking	F1
[2] Mounting Flange on Spindle	F1
[3] Removing Flange from Spindle	F2
[4] Installing a New Wheel	F2
[5] Flange, Assembly Drawing and Parts List	F4

G. Outline of Machining with NC Grinding Machine G1

H. Starting and Ending Machining Operation

[1] Voluntary Check	H1
[2] Weekly Check	H1
[3] Monthly Check	H1
[4] Semi-Annual Check	H2
[5] Yearly Check	H2

Z. Drawings