

CAT Power Unit Summary of some drilling Rig in Saudi Arabia

| SN | Rig | Type | 参数 | Series number | | | Remark |
|-----|-------|-------|-------------------|---------------|----------|----------|--------|
| 125 | SP30 | 3512B | 1390KVA 600V 60Hz | PK200110 | 9RZ02005 | PK200110 | |
| 126 | SP30 | 3512B | 1390KVA 600V 60Hz | PK200121 | 9RZ02030 | PK200121 | |
| 127 | SP30 | 3512B | 1390KVA 600V 60Hz | PK200120 | 9RZ02018 | PK200120 | |
| 128 | SP30 | 3512B | 1390KVA 600V 60Hz | PK200123 | 9RZ02021 | PK200123 | |
| 129 | SP30 | 3512B | 1390KVA 600V 60Hz | 9G500155 | BK400171 | 8G500155 | |
| 196 | SP29 | 3512B | 1390KVA 600V 60Hz | PK200114 | 9RZ02013 | PK200114 | |
| 197 | SP29 | 3512B | 1390KVA 600V 60Hz | PK200128 | 9RZ02024 | PK200128 | |
| 198 | SP29 | 3512B | 1390KVA 600V 60Hz | PK200125 | 9RZ02033 | PK200125 | |
| 199 | SP29 | 3512B | 1390KVA 600V 60Hz | 9G500154 | BK400170 | 8G500154 | |
| 200 | SP29 | 3512B | 1390KVA 600V 60Hz | PK200119 | 9RZ02029 | PK200119 | |
| 205 | SP260 | 3512C | 1492KVA 600V 50HZ | LM900139 | BE400285 | LM800138 | |

华北国际合作231125 / 华北沙特60HZ柴油机铭牌231126

二批通知SP29队3512B铭牌

首批通知3512B铭牌

第1台 PK200110

9G500154

第2台 PK200123

PK200114

第3台 PK200120

PK200119

第4台 PK200121

PK200125

第5台 8G500155

PK200128

PK200131 PIPs/PSPs Product Configuration Product Coverage Customer Name and Address

| | |
|---|--|
| Arrangement No: 506-7561 Mfg Model: 3512B Mktg Model Year: 2017 Prod Family: ZN 3500 Engines Sims Prod Family: 44 Generator Set Source Facility: 88 Lafayette Plant Principle Work: B12 Drilling | Build Date: 28Oct2016 Factory Ship Date: Not Applicable Dealer/Invoiced Ship Date: 19Nov2016 Sales Date: 30Mar2017 Delivery Date: None Selling Dir: J440 Owner CIs: B |
|---|--|

Engine Information
Specifications
Application
 E Prime Power

15 Rows Displayed

Service History

3 results found, displaying 1 to 3

| View Image | Add Image | Group Number | Part Causing Failure | Repairing Dealer | Service Meter Measurement | Repair Date | SIMS Ticket Received | Claim Received | Work Order Number | Dealer Claim Number | Service Claim Number | Comment |
|------------|-----------|--------------|----------------------|------------------|---------------------------|-------------|----------------------|----------------|-------------------|---------------------|----------------------|---------------------|
| | Add | 1452 | No Part Number | J440 | 15 Hours | 11Dec2024 | SIMS Rcvd | No Claim Rcvd | | | | |
| | Add | 7769 | No Part Number | J440 | 1 Hours | 23Dec2021 | SIMS Rcvd | No Claim Rcvd | FPS | | | Fps - Reason Code 4 |
| | Add | 7589 | No Part Number | J440 | 2 Hours | 14Dec2021 | SIMS Rcvd | No Claim Rcvd | SH0E7W4 | | | |