

List of Recommended Spare Parts

Client : Alliance Forest Products U.S. Corp.

Order Number : 445020

Continental Reference : FT-00-1217

Equipment : Curved Belt Conveyor

Description	Continental Part Number	G.A. Drawing Item Number	Recom. Qty	Unit Price US \$
		TD-110-538D		

Tail pulley 18" dia. 48" C.F.	TA-450-881A-6	101	1	454.25 \$
Take-up pulley 18" dia. X 48" C.F.	TA-450-881A-7	102		
Bend pulley 14" face X 48" C.F. c/w 3/8" plain lag	TA-450-881A-8	103	1	591.75
Snub pulley 14" dia. X 48" C.F. c/w 3/8" plain lag.	TA-450-881A-10	105		
Drive pulley 316L 24" dia. x 48" C.F. c/w 14 mm cer. ceramic	TA-450-881A-9	104	1	4176.25
Pillow Block SKF 3-7/16" #FSAFD-520-307 LER (5 O.E.C. & 1 B.E.O.)	TD-110-538D-111	111	2	324.00
Pillow Block SKF 3-15/16" #FSAFD-522-315 LER (7 O.E.C. & 1 O.E.C.)	TD-110-538D-112	112	2	380.50
Pillow Block SKF 4-15/16" #FSAFD-528-415 LER (1 O.E.C. & 1 B.E.O.)	TD-110-538D-113	113	2	725.50
Replacement rolls for BB-3020-5-42 x 5" dia.	BBTR520250389A4	114	20	44.50
Replacement rolls for BB-3045-5-42 x 5" dia.	BBTR520250389A4	115		
Replacement rolls for pos. action 45° troughing idler #BB-3145-5-42SP (special)	BBTR520250389A4	117		
Replacement rolls for special tilting 45° troughing idler	BBTR520250389A4	116A 116B	30	44.50
Replacement rolls for special tilting 45° troughing idler	BBTR520250389A4			
Replacement rolls for special tilting 45° troughing idler	BBTR520200175A4	116A	5	36.75
Replacement rolls for special tilting 45° troughing idler	BBTR520200175A4	116B		
Replacement rolls for return idler #BB-3010-5-42 x 5" dia. (reverse crank)	BBRR20251140A4	118	5	61.50 \$

List of Recommended Spare Parts

Client : Alliance Forest Products U.S. Corp.

Order Number : 445020

Continental Reference : FT-00-1217

Equipment : Curved Belt Conveyor

Description	Continental Part Number	G.A. Drawing Item Number	Recom. Qty	Unit Price US \$
		TD-110-538D		
Replacement rolls for positive action return idler #BB-3110-5-42 x 5" dia.	BBRR20251140A4	119		
Replacement rolls for special V return idler	BBRR520250760A4	120	15	53.00
Replacement rolls for return belt idler #BB-4010-5-42 x 5" dia. (reverse crank)	BBRR525301140A4	157	1	69.25
Replacement blades for "V" type belt cleaner	TD-470-042D-42	122	1	140.00
Replacement blades for belt pre-cleaner confiflex (tungsten blade)	TD-470-244D-42-325-T	123	5	80.00
Replacement blades for belt pre-cleaner confiflex (tungsten blade)	TD-470-246D-42-T	124	5	80.00
Reducer Hansen #SKZH95C.28-1, right angle hollow shaft c/w keyway, ratio 28:1, mount "R", mount pos. 1 bored for 4-1/2" dia. shaft Alliance part number : T94380	TD-110-538D-133	133	1	9375.00

The quoted prices are valid for a period of 90 days from date of issue.

/ag