

CAN AM VOITH COMBISORTER FOR REBUILD MTR MARTCO DRAWING #610-D-267 JOB #57140-K



PICTURE BEFORE REBUILD

INITIAL INSPECTION REPORT:

- ROTOR IS IN POOR CONDITION. VANES ARE THE WRONG SHAPE.
- ORIFICE PLATE NEEDS NEW BANGOR BARS.
- EXTRACTION PLATE IS TOO WORN TO RECONDITION.
- THE BASKETS ARE BAD.
- DRIVE SHAFT IS BAD.
- THE CHAMBER DOES NOT HAVE TILE. IT HAS BEEN HARDCOATED. WE WON'T BE ABLE TO PUT TILE IN IT BECAUSE THERE IS NOT ENOUGH ROOM.
- ALL ANGLE FACE RINGS & BACKUP FLANGES ON CHAMBER ARE BAD.
- THE DISCHARGE FLIGHTS (2) ON THE DRUM ROTOR ARE BAD.
- THE DRIVE HOUSING IS GOOD.
- BASKET RETAINER PLATE IS MISSING
- ROTOR END CAP IS GOOD.
- DRIVE END CAP IS GOOD.
- ROTOR SPACER IS GOOD.
- THRUST PLATE IS GOOD.
- BODY IS GOOD.
- ALL BEARING SPACERS & SEAL RINGS IN DRIVE ARE BAD OR MISSING.

SCOPE OF REBUILD:

- DISMANTLE COMBISORTER COMPLETE.
- CLEAN & DEGREASE ALL PARTS FOR INSPECTION.
- INSPECT FOR REPAIRS & RECORD ON INSPECTION REPORT.
- MACHINE NEW SHAFT & KEYS.
- MAKE & INSTALL NEW BANGOR BARS ON EXISTING ORIFICE PLATE.
- INSTALL ALL NEW ANGLE FACE RINGS & BACKUP FLANGES ON CHAMBER.
- COAT HARDCOATED AREA INSIDE CHAMBER WITH CERAMIC EPOXY.
- MACHINE ALL NEW BEARING SPACERS & SEAL RINGS.
- MACHINE NEW BASKET RETAINER PLATE.
- FABRICATE & MACHINE (2) NEW DISCHARGE FLIGHTS.
- SQUARE UP WORN AREAS OF VANES ON THE DRUM & RE-MACHINE.
- INSTALL NEW THREADED RODS, HEX NUTS & WASHERS ON FRAME.
- BLAST, PRIME & PAINT WITH EPOXY PAINT:

MAIN FRAME & MOTOR MOUNT PLATE

BEARING HOUSING

BEAD BLAST STAINLESS & PAINT CARBON STEEL PARTS WITH EPOXY PAINT:

CHAMBER

BODY

ASSEMBLE DRIVE CARTRIDGE COMPLETE:

NEW:

SHAFT

SHAFT KEYS

BEARING SPACERS & SEAL RINGS

BEARINGS

O-RINGS

LOCKNUTS & LOCKWASHERS

SEALS

FASTENERS

RE-USE:

HOUSING

ROTOR END CAP

DRIVE END CAP

ASSEMBLE COMBISORTER COMPLETE:

NEW:

EXTRACTION PLATE WITH SUPPORT RINGS

UPPER & LOWER BASKET ASSEMBLY

BASKET RETAINER PLATE

ROTOR

DISCHARGE FLIGHTS

O-RINGS

FASTENERS

SHIM

RE-USE:

BODY

ROTOR SPACER

THRUST PLATE

ORIFICE PLATE (WITH NEW BANGORS)

CHAMBER (REPAIRED)

DRUM ROTOR (REPAIRED)

FRAME (W/NEW THREADED RODS & FASTENERS) BELT SHEAVE & QD BUSHING (SHIPPED LOOSE)

- SHIM ASSEMBLY FOR CORRECT RUNNING CLEARANCE (XTRA SHIM TO BE SENT WITH UNIT)
- TOUCH-UP PAINT AS REQUIRED.
- APPLY ALL TAGGING & DECALS.



06-30-2020