

CNC VERTICAL MACHINING CENTER

EXCEL-810

WITH FANUC OM

PARTS LIST



PARTS LIST
EXCEL 810

	NO.	PAGE
Spindle unit	K0601-17-1	1
Spindle head body	K0601-17-2	6
Z axis and column	K0601-18-1	8
X, Y, Z axis dog	K0601-18-2	12
Y axis and bed, saddle, table	K0601-19-1	14
X axis and bed, saddle, table	K0601-19-2	17
ATC magazine	K0601-20-1	21
ATC double arm box (A)	K0601-20-2	25
ATC double arm box (B)	K0601-21-1	28
ATC double arm	K0601-21-2	31
ATC 24 double arm and magazine	K1101-20-1	33
ATC tool pusher	K1101-20-2	35